

Date 12/22/2023
Make Model Cirrus SR22T

Tail # N75T

Serial # 9007

Airworthiness Directive
Compliance Report

Airframe Hours: Flight Hobbs: 209.1 / Hobbs: 260.1

Misc:

Engine: Continental TSIO-550-K

S/N: 1044328

Hours:

Propeller: Hartzell 4C1

S/N: TM299

Hours:

AD#	Category	Subject	Amend #	Eff Date	Rec	Remarks
Date/Hours Compliance		Next Due	Signature	Cert#		
Airframe: Cirrus SR22T						
12-01-11	Airframe	Induction System Air Box Seals	39-16923	02/29/12		NA by S/N
23-09-09	Airframe	Exhaust Tailpipe V-Band Coupling	39-22432	07/17/23	Yes	Complied with visual inspection per detailed AD instructions in paragraph (k)(1)-(7). Next Due: 6 months/100 Hr, whichever is first. Replace V-Band Couplings as soon as they become available.
Engine: Continental TSIO-550-K						
10-11-04	Engine	Hydraulic Lifter Face Wear	39-16309	06/16/10		NA by S/N specified in Section A of TCM Mandatory Service Bulletin (MSB) No. MSB09-8A, dated December 4, 2009.
12-03-06	Engine	AVStar Fuel Servo Diaphragm	39-16947	02/24/12		NA, AVStar Fuel Systems, Inc. (AFS) fuel servo diaphragm not installed
12-10-13	Engine	Starter Adaptor Gear Shaft	39-17062	06/08/12		NA, Engine manufactured after November 20, 2011
16-16-12	Engine	AEC/CMI Cylinder Assemblies	39-18610	09/15/16		NA, cylinders not installed. Verified via "Engine Component Information Sheet" printed 10/24/2022. Filed with engine log books.
16-21-04	Engine	Oil Cooler Cross Fitting	39-18685	11/18/16		NA by engine S/N
20-16-11	Engine	Cross-Flow Cylinder Assembly Fractures	39-21195	09/21/20		NA by cylinder S/N specified in "Continental Aerospace Technologies MSB18-08B". Visually confirmed cylinders require no further action per detailed visual inspection of the cross-flow cylinder assembly using paragraphs III.1 through III.3, Action Required, of Continental Aerospace Technologies, Inc. Mandatory Service Bulletin (MSB) 18-08, Revision B, dated January 13, 2020
23-02-12	Engine	Intake Valve Failures	39-22319	02/17/23		NA by part number (P/N) and serial number listed in Table 1 of Superior Air Parts, Inc. MSB22-01 A
23-05-16	Engine	Crankshaft Counterweight Retaining Rings	39-22385	03/15/23		AD 2023-04-08 (superseded) & MSB23-01 Rev A, PCW. Log Dated: 03/02/2023
23-09-09	Engine	Exhaust Tailpipe V-Band Coupling	39-22432	07/17/23	Yes	Complied with visual inspection per detailed AD instructions in paragraph (k)(1)-(7). Next Due: 6 months/100 Hr, whichever is first. Replace V-Band Couplings as soon as they become available.