

Work Order - Workflow

Location: OxfordSaudia
Resource Category: Aircraft

Site: All
Resource Type: DA-40NG
W/O #: All

27 August 2019 TO 11 February 2024
Resource: XF-35

Work Order	2020 00487	Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details
07 Dec 2020 08:19	Opened	FREEMAN, TIM	
07 Dec 2020 08:19	Discrepancy Added	FREEMAN, TIM	INSTALL AIRCRAFT REGISTRATION MARKS HZ-XF35
07 Dec 2020 08:47	Closed	FREEMAN, TIM	

Work Order 2020 00488			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
07 Dec 2020	08:51	Opened	FREEMAN, TIM			
07 Dec 2020	08:51	Discrepancy Added	FREEMAN, TIM		INSTALL AIRCRAFT REGISTRATION MARKINGS HZ-XF35	
06 Oct 2021	10:45	Closed	FREEMAN, TIM			

Work Order 2020 00489			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
07 Dec 2020 09:33	Opened	FREEMAN, TIM		
07 Dec 2020 09:33	Discrepancy Added	FREEMAN, TIM	INSTALL RESOURCE PARTS FOR RMS TRACKING.	
28 Dec 2020 12:32	Parts Posted	FREEMAN, TIM		
28 Dec 2020 12:33	Part Filled	FREEMAN, TIM	(1) 011-00878-20 serial # 1A1024875	
28 Dec 2020 12:34	Part Filled	FREEMAN, TIM	(1) 011-00878-20 serial # 1A1024922	
28 Dec 2020 12:34	Part Filled	FREEMAN, TIM	(1) 011-00878-20 serial # 1A1025604	
28 Dec 2020 12:34	Part Filled	FREEMAN, TIM	(1) 011-01904-03 serial # 28K009909	
28 Dec 2020 12:34	Part Filled	FREEMAN, TIM	(1) 011-01904-03 serial # 28K009701	
28 Dec 2020 12:34	Part Filled	FREEMAN, TIM	(1) 011-01904-03 serial # 28K009769	
28 Dec 2020 12:35	Part Filled	FREEMAN, TIM	(1) RG24-15 serial # XF35	
28 Dec 2020 12:35	Part Filled	FREEMAN, TIM	(1) ES-10024B-2 serial # H-S050270	
28 Dec 2020 12:35	Part Filled	FREEMAN, TIM	(1) 18002-B serial # XF35	
28 Dec 2020 12:35	Part Filled	FREEMAN, TIM	(1) PST-305 serial # AS06201212	
28 Dec 2020 12:35	Part Filled	FREEMAN, TIM	(1) E4A-93-000-000	
28 Dec 2020 12:36	Part Filled	FREEMAN, TIM	(1) E4A-91-400-000 serial # 02911	
28 Dec 2020 12:36	Part Filled	FREEMAN, TIM	(1) MTV-6-R/190-69 serial # 200520	
28 Dec 2020 12:36	Part Filled	FREEMAN, TIM	(1) P-853-16 serial # 20G677-K/G	
28 Dec 2020 12:36	Part Filled	FREEMAN, TIM	(1) E4A-00-000-000 serial # E4A-A-06007	
28 Dec 2020 12:36	Part Filled	FREEMAN, TIM	(1) E4A-33-100-000 serial # 1913500143	
28 Dec 2020 12:37	Part Filled	FREEMAN, TIM	(1) E4A-00-410-000 serial # WA5003947100053	
28 Dec 2020 12:37	Part Filled	FREEMAN, TIM	(1) E4A-73-300-000 serial # 04465	
28 Dec 2020 12:37	Part Filled	FREEMAN, TIM	(1) D44-9081-26-02_01 serial # 817R-A20	
28 Dec 2020 12:37	Part Filled	FREEMAN, TIM	(1) D44-7521-00-00_3	
28 Dec 2020 12:38	Part Filled	FREEMAN, TIM	(1) IDAU-001 EPA serial # 20190059	
28 Dec 2020 12:38	Part Filled	FREEMAN, TIM	(1) APISD-001 EPA serial # 20200008	
28 Dec 2020 12:38	Part Filled	FREEMAN, TIM	(1) I1003-001 EPA serial # 202000023	
28 Dec 2020 12:38	Part Filled	FREEMAN, TIM	(1) I1500-002 EPA serial # 19P083673	
28 Dec 2020 12:38	Part Filled	FREEMAN, TIM	(1) I1101-001 EPA serial # 20200009	
28 Dec 2020 12:38	Part Filled	FREEMAN, TIM	(1) I1101-002 EPA serial # 20200015	
28 Dec 2020 12:39	Part Filled	FREEMAN, TIM	(1) IDRMU-001 EPA serial # 20190057	
28 Dec 2020 12:39	Part Filled	FREEMAN, TIM	(1) 011-03470-00 serial # 494006462	
28 Dec 2020 12:39	Part Filled	FREEMAN, TIM	(1) 011-03470-60 serial # 494605111	
28 Dec 2020 12:39	Part Filled	FREEMAN, TIM	(1) 011-03711-00 serial # 45K010241	
28 Dec 2020 12:39	Part Filled	FREEMAN, TIM	(1) 011-03711-00 serial # 45K010283	
28 Dec 2020 12:39	Part Filled	FREEMAN, TIM	(1) 5934PD-3 serial # 518191	
28 Dec 2020 12:40	Part Filled	FREEMAN, TIM	(1) 8025 CODE B.908 serial # 220312	
28 Dec 2020 12:40	Part Filled	FREEMAN, TIM	(1) 4300-206 serial # B20-10773	
28 Dec 2020 12:40	Part Filled	FREEMAN, TIM	(1) 011-00978-00 serial # 47954256	

Work Order			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
28 Dec 2020 12:40	Part Filled	FREEMAN, TIM	(1) 011-00870-10 serial # 1CM033850	
28 Dec 2020 12:40	Part Filled	FREEMAN, TIM	(1) 066-1070-01 serial # 44394	
28 Dec 2020 12:41	Part Filled	FREEMAN, TIM	(1) 0505.757-912 serial # 04580	
28 Dec 2020 12:41	Part Filled	FREEMAN, TIM	(1) 0856.010-912 serial # 02361	
28 Dec 2020 12:41	Part Filled	FREEMAN, TIM	(1) 0832.601-912 serial # 05312	
28 Dec 2020 12:41	Part Filled	FREEMAN, TIM	(1) 70-2420-X TAS605 serial # M200372360	
28 Dec 2020 12:41	Part Filled	FREEMAN, TIM	(1) 70-2420 serial # M201376131	
28 Dec 2020 12:41	Part Filled	FREEMAN, TIM	(1) S72-1750-31L serial # 13903	
28 Dec 2020 12:42	Part Filled	FREEMAN, TIM	(1) S72-1750-32L serial # 14037	
28 Dec 2020 12:42	Part Filled	FREEMAN, TIM	(1) E4A-94-200-000 serial # 003820	
28 Dec 2020 12:42	Part Filled	FREEMAN, TIM	(1) E4A-70-000-000 serial # 3762	
28 Dec 2020 12:42	Part Filled	FREEMAN, TIM	(1) E4A-30-000-000 serial # 20-03-04-02-00086	
28 Dec 2020 12:42	Part Filled	FREEMAN, TIM	(1) D44-7126-10-00_5 serial # 653	
28 Dec 2020 12:42	Part Filled	FREEMAN, TIM	(1) D44-9075-20-01_01 serial # 731R-C20	
28 Dec 2020 12:43	Part Filled	FREEMAN, TIM	(1) i3031-001 EPA serial # 202000011A	
28 Dec 2020 12:43	Part Filled	FREEMAN, TIM	(1) i3031-001 EPA serial # 202000010M	
28 Dec 2020 12:43	Part Filled	FREEMAN, TIM	(1) 011-03734-00 serial # 45S002762	
28 Dec 2020 12:43	Part Removed from Work Order	FREEMAN, TIM	(1) i3031-001 EPA serial # 202000011A	
28 Dec 2020 12:44	Part Removed from Work Order	FREEMAN, TIM	(1) i3031-001 EPA serial # 202000010M	
28 Dec 2020 12:44	Part Filled	FREEMAN, TIM	(1) 011-03732-00 serial # 45T003872	
28 Dec 2020 12:44	Part Filled	FREEMAN, TIM	(1) 011-03568-00 serial # 4QF006192	
28 Dec 2020 12:44	Part Filled	FREEMAN, TIM	(1) 011-03682-00 serial # 497004689	
28 Dec 2020 12:44	Part Filled	FREEMAN, TIM	(1) 011-03303-00 serial # 3EH028121	
28 Dec 2020 12:45	Part Filled	FREEMAN, TIM	(1) 305-467-00	
28 Dec 2020 12:45	Part Filled	FREEMAN, TIM	(2) 011-02147-15	
28 Dec 2020 12:45	Part Filled	FREEMAN, TIM	(1) D44-2416-20-00	
28 Dec 2020 12:46	Part Filled	FREEMAN, TIM	(3) 013-00244-00	
28 Dec 2020 12:46	Part Filled	FREEMAN, TIM	(1) 200-09187-0000	
28 Dec 2020 12:46	Part Filled	FREEMAN, TIM	(2) 305-468-00	
28 Dec 2020 12:46	Part Filled	FREEMAN, TIM	(1) 011-02147-08	
28 Dec 2020 12:46	Part Filled	FREEMAN, TIM	(1) DA4-2213-12-90	
28 Dec 2020 12:46	Part Filled	FREEMAN, TIM	(1) 031-00514-0000	
28 Dec 2020 12:47	Part Filled	FREEMAN, TIM	(1) 031-00428-0000	
28 Dec 2020 12:47	Part Filled	FREEMAN, TIM	(1) D60-2560-91-00	
28 Dec 2020 12:47	Part Filled	FREEMAN, TIM	(1) DA4-2443-10-00	
28 Dec 2020 12:47	Part Filled	FREEMAN, TIM	(1) D44-2416-00-52_1	
28 Dec 2020 12:47	Part Filled	FREEMAN, TIM	(1) ISO 4184 XPZ L987	
28 Dec 2020 12:47	Part Filled	FREEMAN, TIM	(1) D44-2153-00-00	

Work Order			Work Order Status: Closed	Resource: XF-35
When	Action		Who	Details
28 Dec 2020 12:48	Part Filled		FREEMAN, TIM	(1) E4A-92-100-000 serial #
28 Dec 2020 12:48	Part Filled		FREEMAN, TIM	(1) 01-0771733-11
28 Dec 2020 12:48	Part Filled		FREEMAN, TIM	(1) A 620 T
28 Dec 2020 12:48	Part Filled		FREEMAN, TIM	(1) OEN_V_5101_
28 Dec 2020 12:48	Part Filled		FREEMAN, TIM	(1) 43055
28 Dec 2020 12:48	Part Filled		FREEMAN, TIM	(1) DA4-2739-10-00X04
28 Dec 2020 12:49	Part Filled		FREEMAN, TIM	(1) 01-0771125-23
28 Dec 2020 12:49	Part Filled		FREEMAN, TIM	(1) 01-0771125-20
28 Dec 2020 12:49	Part Filled		FREEMAN, TIM	(1) APVL328-4-1-L-5QF
28 Dec 2020 12:49	Part Filled		FREEMAN, TIM	(1) APVL328-4-1-L-15QF
28 Dec 2020 12:49	Part Filled		FREEMAN, TIM	(1) CI 291
28 Dec 2020 12:49	Part Filled		FREEMAN, TIM	(1) CI 292-2
28 Dec 2020 12:50	Part Filled		FREEMAN, TIM	(1) 62800-001
28 Dec 2020 12:50	Part Filled		FREEMAN, TIM	(1) DA4-3111-51-00
28 Dec 2020 12:50	Part Filled		FREEMAN, TIM	(1) E4A-91-200-000
28 Dec 2020 12:50	Part Filled		FREEMAN, TIM	(2) 0-580-054-001
28 Dec 2020 12:50	Part Filled		FREEMAN, TIM	(1) D44-7806-20-00_2
28 Dec 2020 12:51	Part Filled		FREEMAN, TIM	(2) D4D-2817-13-00X01
28 Dec 2020 12:51	Part Filled		FREEMAN, TIM	(1) D4D-2807-11-00
28 Dec 2020 12:51	Part Filled		FREEMAN, TIM	(1) D4D-2807-12-00
28 Dec 2020 12:51	Part Filled		FREEMAN, TIM	(1) E4A-92-200-000
28 Dec 2020 12:51	Part Filled		FREEMAN, TIM	(1) D44-7306-30-00_1
28 Dec 2020 12:51	Part Filled		FREEMAN, TIM	(1) A24119-01
28 Dec 2020 12:52	Part Filled		FREEMAN, TIM	(2) LC-R127R2PG
28 Dec 2020 12:52	Part Filled		FREEMAN, TIM	(1) VR2000-28-1
28 Dec 2020 12:52	Part Filled		FREEMAN, TIM	(1) 5-01-1C0701
28 Dec 2020 12:52	Part Filled		FREEMAN, TIM	(1) 5-01-1C5701
28 Dec 2020 12:52	Part Filled		FREEMAN, TIM	(1) 5-01-1B5701
28 Dec 2020 12:52	Part Filled		FREEMAN, TIM	(1) 5-01-1B0701
28 Dec 2020 12:53	Part Filled		FREEMAN, TIM	(1) 85094-12
28 Dec 2020 12:53	Part Filled		FREEMAN, TIM	(1) WW-LCM002
28 Dec 2020 12:53	Part Filled		FREEMAN, TIM	(1) 10-54A
28 Dec 2020 12:53	Part Filled		FREEMAN, TIM	(1) 60-5D
28 Dec 2020 12:54	Part Filled		FREEMAN, TIM	(1) 30-239B
28 Dec 2020 12:54	Part Filled		FREEMAN, TIM	(1) D44-3229-29-00_1
28 Dec 2020 12:54	Part Filled		FREEMAN, TIM	(1) 01-0771733-12
28 Dec 2020 12:54	Part Filled		FREEMAN, TIM	(1) RL6980-1
28 Dec 2020 12:54	Part Filled		FREEMAN, TIM	(1) PG2C-28V

Work Order			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
28 Dec 2020 12:55	Part Filled	FREEMAN, TIM	(1) C1-157P	
28 Dec 2020 12:55	Part Filled	FREEMAN, TIM	(1) CI-1125	
28 Dec 2020 12:55	Part Filled	FREEMAN, TIM	(1) CI 102	
28 Dec 2020 12:56	Part Filled	FREEMAN, TIM	(4) E4A-35-000-000	
28 Dec 2020 12:56	Part Filled	FREEMAN, TIM	(1) E4A-95-000-000	
28 Dec 2020 12:57	Parts Posted	FREEMAN, TIM		
28 Dec 2020 12:58	Parts Posted	FREEMAN, TIM		
28 Dec 2020 13:01	Part Filled	FREEMAN, TIM	(1) i3031-001 EPA serial # 20200007M	
28 Dec 2020 13:01	Part Filled	FREEMAN, TIM	(1) i3031-001 EPA serial # 202000011M	
28 Dec 2020 13:02	Part Filled	FREEMAN, TIM	(1) 30-239B	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) RG24-15 serial # XF35	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-30-000-000 serial # 20-03-04-02-00086	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(4) E4A-35-000-000	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(2) LC-R127R2PG	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) APVL328-4-1-L-15QF	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) APVL328-4-1-L-5QF	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 18002-B serial # XF35	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(2) D4D-2817-13-00X01	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-00878-20 serial # 1A1024875	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-00878-20 serial # 1A1024922	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-00878-20 serial # 1A1025604	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-01904-03 serial # 28K009909	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-01904-03 serial # 28K009701	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-01904-03 serial # 28K009769	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 305-467-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(2) 305-468-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-91-400-000 serial # 02911	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(2) 011-02147-15	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-02147-08	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) DA4-2213-12-90	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 031-00514-0000	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 031-00428-0000	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 200-09187-0000	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D60-2560-91-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) DA4-2443-10-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) ES-10024B-2 serial # H-S050270	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-2416-20-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-2416-00-52_1	

Work Order		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) ISO 4184 XPZ L987	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) VR2000-28-1	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-2153-00-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 5-01-1C0701	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 5-01-1C5701	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 5-01-1B5701	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 5-01-1B0701	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) A 620 T	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 43055	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) DA4-2739-10-00X04	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 85094-12	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 10-54A	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 60-5D	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 30-239B	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 30-239B	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-3229-29-00_1	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 01-0771733-11	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 01-0771125-23	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 01-0771125-20	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) RL6980-1	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) CI 292-2	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 62800-001	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) PST-305 serial # AS06201212	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) DA4-3111-51-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 5934PD-3 serial # 518191	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 8025 CODE B.908 serial # 220312	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 4300-206 serial # B20-10773	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-00978-00 serial # 47954256	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-00870-10 serial # 1CM033850	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(3) 013-00244-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 0856.010-912 serial # 02361	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 70-2420 serial # M201376131	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) S72-1750-32L serial # 14037	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-00-000-000 serial # E4A-A-06007	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-92-100-000 serial #	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-94-200-000 serial # 003820	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-93-000-000	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-91-200-000	

Work Order		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(2) 0-580-054-001	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-7806-20-00_2	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) MTV-6-R/190-69 serial # 200520	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) P-853-16 serial # 20G677-K/G	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D4D-2807-11-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D4D-2807-12-00	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 01-0771733-12	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) S72-1750-31L serial # 13903	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-03470-00 serial # 494006462	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-03470-60 serial # 494605111	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-03568-00 serial # 4QF006192	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-03682-00 serial # 497004689	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-03711-00 serial # 45K010241	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-03711-00 serial # 45K010283	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-03732-00 serial # 45T003872	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-03734-00 serial # 45S002762	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 0832.601-912 serial # 05312	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 70-2420-X TAS605 serial # M200372360	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) APISD-001 EPA serial # 20200008	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) I1003-001 EPA serial # 202000023	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) I1500-002 EPA serial # 19P083673	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) IDAU-001 EPA serial # 20190059	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) IDRMU-001 EPA serial # 20190057	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) PG2C-28V	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) WW-LCM002	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-7126-10-00_5 serial # 653	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-7521-00-00_3	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-9075-20-01_01 serial # 731R-C20	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-9081-26-02_01 serial # 817R-A20	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-00-410-000 serial # WA5003947100053	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-33-100-000 serial # 1913500143	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-70-000-000 serial # 3762	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-73-300-000 serial # 04465	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-95-000-000	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 066-1070-01 serial # 44394	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 0505.757-912 serial # 04580	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) I1101-001 EPA serial # 20200009	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) I1101-002 EPA serial # 20200015	

Work Order		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) E4A-92-200-000	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) i3031-001 EPA serial # 202000011M	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) i3031-001 EPA serial # 20200007M	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) CI 291	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) D44-7306-30-00_1	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) C1-157P	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) CI 102	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 011-03303-00 serial # 3EH028121	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) CI-1125	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) A24119-01	
03 Jan 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) OEN_V_5101_	
03 Jan 2021 09:33	Closed	FREEMAN, TIM		
31 Aug 2021 06:47	Parts Posted	FREEMAN, TIM		
31 Aug 2021 06:51	Parts Posted	FREEMAN, TIM		
31 Aug 2021 07:26	Parts Posted	FREEMAN, TIM		
01 Sep 2021 05:55	Part Filled	ALENAZI, NAFEL	(1) 305-467-00	
01 Sep 2021 05:55	Part Installed on Resource	ALENAZI, NAFEL	(1) 305-467-00	
01 Sep 2021 06:28	Part Removed from Closed Work	ALENAZI, NAFEL	(1) 305-467-00	
01 Sep 2021 09:29	Parts Posted	FREEMAN, TIM		
01 Sep 2021 09:30	Part Filled	FREEMAN, TIM	(1) E4A-09-000-901	
01 Sep 2021 09:30	Part Installed on Resource	FREEMAN, TIM	(1) E4A-09-000-901	
01 Sep 2021 09:30	Part Filled	FREEMAN, TIM	(1) E4A-00-410-BHY serial # WA5003947100053	
01 Sep 2021 09:30	Part Installed on Resource	FREEMAN, TIM	(1) E4A-00-410-BHY serial # WA5003947100053	
01 Sep 2021 09:31	Part Filled	FREEMAN, TIM	(1) E4A-92-000-000 serial # 3583	
01 Sep 2021 09:31	Part Installed on Resource	FREEMAN, TIM	(1) E4A-92-000-000 serial # 3583	
01 Sep 2021 09:32	Part Filled	FREEMAN, TIM	(1) 453-6603 serial # 242-08569	
01 Sep 2021 09:32	Part Installed on Resource	FREEMAN, TIM	(1) 453-6603 serial # 242-08569	
01 Sep 2021 09:32	Part Filled	FREEMAN, TIM	(1) 452-6505	
01 Sep 2021 09:32	Part Installed on Resource	FREEMAN, TIM	(1) 452-6505	
01 Sep 2021 09:32	Part Filled	FREEMAN, TIM	(1) D4D-2807-90-00	
01 Sep 2021 09:32	Part Installed on Resource	FREEMAN, TIM	(1) D4D-2807-90-00	
01 Sep 2021 09:32	Part Filled	FREEMAN, TIM	(1) 031-00428-0000	
01 Sep 2021 09:32	Part Installed on Resource	FREEMAN, TIM	(1) 031-00428-0000	
01 Sep 2021 09:32	Part Filled	FREEMAN, TIM	(1) 354-6196-04	
01 Sep 2021 09:32	Part Installed on Resource	FREEMAN, TIM	(1) 354-6196-04	
01 Sep 2021 09:33	Part Filled	FREEMAN, TIM	(1) 110-773	
01 Sep 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) 110-773	

Work Order		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
01 Sep 2021 09:33	Part Filled	FREEMAN, TIM	(1) DA4-2213-12-90	
01 Sep 2021 09:33	Part Installed on Resource	FREEMAN, TIM	(1) DA4-2213-12-90	
01 Sep 2021 11:03	Parts Posted	FREEMAN, TIM		
02 Sep 2021 11:34	Part Filled	FREEMAN, TIM	(1) RG24-15 serial # XF35	
02 Sep 2021 11:34	Part Installed on Resource	FREEMAN, TIM	(1) RG24-15 serial # XF35	
02 Sep 2021 11:38	Part Removed from Closed Work	FREEMAN, TIM	(3) 013-00244-00	
02 Sep 2021 11:38	Parts Posted	FREEMAN, TIM		
02 Sep 2021 11:38	Part Filled	FREEMAN, TIM	(2) 013-00244-00	
02 Sep 2021 11:38	Part Installed on Resource	FREEMAN, TIM	(2) 013-00244-00	
07 Sep 2021 05:34	Parts Posted	FREEMAN, TIM		
07 Sep 2021 05:35	Part Removed from Closed Work	FREEMAN, TIM	(1) A 620 T	
07 Sep 2021 06:01	Parts Posted	FREEMAN, TIM		
07 Sep 2021 06:05	Part Filled	FREEMAN, TIM	(1) P853-16 serial # 20G677-K/G	
07 Sep 2021 06:05	Part Installed on Resource	FREEMAN, TIM	(1) P853-16 serial # 20G677-K/G	
07 Sep 2021 06:05	Part Filled	FREEMAN, TIM	(1) 110-773	
07 Sep 2021 06:05	Part Installed on Resource	FREEMAN, TIM	(1) 110-773	
07 Sep 2021 06:06	Part Filled	FREEMAN, TIM	(1) E4A-00-000-000 serial # E4A-A-06007	
07 Sep 2021 06:06	Part Installed on Resource	FREEMAN, TIM	(1) E4A-00-000-000 serial # E4A-A-06007	
07 Sep 2021 10:30	Part Removed from Closed Work	FREEMAN, TIM	(1) 110-773	
07 Sep 2021 10:33	Part Removed from Closed Work	FREEMAN, TIM	(1) E4A-00-000-000 serial # E4A-A-06007	
06 Oct 2021 10:39	Closed	FREEMAN, TIM		
26 Nov 2021 10:18	Parts Posted	FREEMAN, TIM		
26 Nov 2021 10:19	Part Filled	FREEMAN, TIM	(1) DAI-9206-20-01X01 serial # 2	
26 Nov 2021 10:19	Part Installed on Resource	FREEMAN, TIM	(1) DAI-9206-20-01X01 serial # 2	

Work Order 2020 00504		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
17 Dec 2020 04:58	Opened	FREEMAN, TIM		
17 Dec 2020 04:58	Discrepancy Added	FREEMAN, TIM	PERFORM AD, SB, MSB RESEARCH AND COMPLY AS REQUIRED PER EASA AND FAA REQUIREMENTS	
06 Oct 2021 10:42	Closed	FREEMAN, TIM		

Work Order 2021 00134			Work Order Status: Closed		Resource: XF-35	
When	Action		Who	Details		
19 Apr 2021 03:52	Opened		GADZAMA, SAMUEL			
19 Apr 2021 03:52	Discrepancy Added		GADZAMA, SAMUEL	REMOVE EMERGENCY BATTERY PACK FOR USE ON HZ-XF4		
09 Oct 2021 02:04	Discrepancy Added		PEREZ, Javier	REMOVED EMERGENCY BATTERY PACK FOR USE ON HZ-XF4		
09 Oct 2021 02:35	Closed		PEREZ, Javier			

Work Order 2021 00191			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
20 May 2021 07:45	Opened	FREEMAN, TIM		
20 May 2021 07:45	Discrepancy Added	FREEMAN, TIM	REMOVE IDRMU-OO1 S/N AND IDAU-001 S/N FOR USE ON HZ-XF6	
20 May 2021 07:46	Discrepancy Added	FREEMAN, TIM	IDRMU AND IDAU REMOVED FOR USE ON HZ-XF6	
20 May 2021 07:50	Part Removed from Resource	FREEMAN, TIM	(1) IDAU-001 EPA serial # 20190059	
20 May 2021 07:52	Part Removed from Resource	FREEMAN, TIM	(1) IDRMU-001 EPA serial # 20190057	
06 Jul 2021 14:52	Parts Posted	GADZAMA, SAMUEL		
06 Jul 2021 14:53	Parts Posted	GADZAMA, SAMUEL		
08 Oct 2021 12:07	Closed	PEREZ, Javier		

Work Order 2021 00291			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
27 Jun 2021	10:21	Opened	GADZAMA, SAMUEL			
27 Jun 2021	10:21	Discrepancy Added	GADZAMA, SAMUEL		REMOVED OVERHEAD DUCT UNIT P/N D44-2150-80-11_01 TO BE USED ON HZ-XF32.	
30 Jun 2021	07:14	Discrepancy Added	FREEMAN, TIM		OVERHEAD AIRDUCT DAMAGED	
08 Oct 2021	12:42	Closed	PEREZ, Javier			

Work Order 2021 00297			Work Order Status: Closed		Resource: XF-35	
When	Action		Who		Details	
30 Jun 2021 07:14	Opened		FREEMAN, TIM			
30 Jun 2021 07:14	Discrepancy Added		FREEMAN, TIM		REMOVE FLOOD LAMP INVERTER TO BE USED ON HZ-XF7.	
30 Jun 2021 07:15	Discrepancy Added		FREEMAN, TIM		AIRCRAFT FLOOD INVERTER REMOVED FOR USE ON HZ-XF7	
08 Oct 2021 12:16	Closed		PEREZ, Javier			

Work Order 2021 00298			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
30 Jun 2021 07:16	Opened	FREEMAN, TIM		
30 Jun 2021 07:16	Discrepancy Added	FREEMAN, TIM	REMOVE AIR CONN CONRTOLLER AND PANEL FOR USE ON HZ-XF5	
30 Jun 2021 07:16	Discrepancy Added	FREEMAN, TIM	AIR CON CONTROLLER AND PANEL DAMAGED	
09 Oct 2021 01:48	Parts Posted	PEREZ, Javier		
11 Oct 2021 07:24	Part Filled	ALENAZI, NAFEL	(1) DAI-9021-00-03_1	
12 Oct 2021 15:10	Part Installed on Resource	FREEMAN, TIM	(1) DAI-9021-00-03_1	
12 Oct 2021 15:10	Closed	FREEMAN, TIM		

Work Order 2021 00299			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
30 Jun 2021	07:17	Opened	FREEMAN, TIM			
30 Jun 2021	07:17	Event Added	FREEMAN, TIM		ACFT INSURANCE DUE	
30 Jun 2021	07:17	Closed	FREEMAN, TIM			

Work Order 2021 00301			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
01 Jul 2021	06:39	Opened	FREEMAN, TIM			
01 Jul 2021	06:39	Discrepancy Added	FREEMAN, TIM		REMOVE STALL WARNING HORN FOR USE ON HZ-XF3	
01 Jul 2021	06:39	Discrepancy Added	FREEMAN, TIM		STALL WARNING HORN INOP	
08 Oct 2021	12:26	Closed	PEREZ, Javier			

Work Order 2021 00304		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
02 Jul 2021 06:50	Opened	FREEMAN, TIM		
02 Jul 2021 06:50	Discrepancy Added	FREEMAN, TIM	REMOVE CO-PILOT SUNVISOR FOR USE ON HZ-XF32	
02 Jul 2021 06:50	Discrepancy Added	FREEMAN, TIM	CO-PILOT SUN VISOR BROKEN	
10 Oct 2021 12:26	Closed	Watlington, Carlos		

Work Order 2021 00313			Work Order Status: Closed		Resource: XF-35	
When	Action		Who		Details	
06 Jul 2021 14:37	Opened		GADZAMA, SAMUEL			
06 Jul 2021 14:37	Discrepancy Added		GADZAMA, SAMUEL		REMOVE STANDBY SLIP INDICATOR FOR USE ON HZ-XF9.	
08 Oct 2021 12:45	Discrepancy Added		PEREZ, Javier		REMOVED STANDBY SLIP INDICATOR FOR USE ON HZ-XF9.	
08 Oct 2021 12:47	Closed		PEREZ, Javier			

Work Order 2021 00375			Work Order Status: Closed		Resource: XF-35	
When	Action		Who	Details		
04 Aug 2021 03:44	Opened		GADZAMA, SAMUEL			
04 Aug 2021 03:44	Discrepancy Added		GADZAMA, SAMUEL	REMOVE ALT. VOLTAGE REGULATOR P/N VR2000-28-1 (D44-2416-60-00) FOR USE ON HZ-XF9.		
30 Aug 2021 05:08	Discrepancy Added		FREEMAN, TIM	ALTERNATE VOLTAGE REGULATOR P/N VR200-28-1 (D44-2416-60-00) INOP. REMOVED FROM HZ-XF9		
08 Oct 2021 12:31	Closed		PEREZ, Javier			

Work Order 2021 00443			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
28 Aug 2021 10:05	Opened	GADZAMA, SAMUEL		
28 Aug 2021 10:05	Discrepancy Added	GADZAMA, SAMUEL	REMOVED ALTERNATOR CABLE P/N D44-2406-16-00 S/N N/A TO BE USED ON HZ-XF8.	
30 Aug 2021 05:05	Discrepancy Added	FREEMAN, TIM	ALTERNATOR CABLE P/N D44-2406-16-00 TERMINAL BROKE.	
09 Oct 2021 02:02	Closed	PEREZ, Javier		

Work Order 2021 00444			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
30 Aug 2021	05:03	Opened	FREEMAN, TIM			
30 Aug 2021	05:03	Event Added	FREEMAN, TIM		FIRE EXTINGUISHER ANNUAL INSPECTION AMEREX	
12 Oct 2021	15:20	Closed	FREEMAN, TIM			

Work Order 2021 00488			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
21 Sep 2021	06:36	Opened	Watlington, Carlos			
21 Sep 2021	06:36	Discrepancy Added	Watlington, Carlos		REMOVED IDRMU-001 EPA FOR USE ON XF2	
07 Oct 2021	12:21	Discrepancy Added	FREEMAN, TIM		IDRMU REMOVED FOR USE ON HZ-XF2	
08 Oct 2021	12:37	Closed	PEREZ, Javier			

Work Order	2021 00517	Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
06 Oct 2021 06:08	Opened	FREEMAN, TIM		
06 Oct 2021 06:08	Discrepancy Added	FREEMAN, TIM	ANNUAL INSPECTION DUE	
06 Oct 2021 10:54	Event Added	FREEMAN, TIM	FIRST AID KIT INSPECTION	
06 Oct 2021 10:54	Event Added	FREEMAN, TIM	MAGNETIC COMPASS	
06 Oct 2021 10:55	Event Added	FREEMAN, TIM	RACC SYSTEM	
06 Oct 2021 10:55	Event Added	FREEMAN, TIM	ELT FUNCTION TEST	
06 Oct 2021 10:55	Event Added	FREEMAN, TIM	100 HOUR AIRFRAME, PROPELLER AND ENGINE INSPECTION	
06 Oct 2021 10:55	Event Added	FREEMAN, TIM	200 HOUR FDR INSPECTION	
06 Oct 2021 10:55	Event Added	FREEMAN, TIM	ECU BATTERY REPLACEMENT	
06 Oct 2021 10:55	Event Added	FREEMAN, TIM	AUTOPILOT GFC700 MECHANICAL CHECK	
06 Oct 2021 10:55	Event Added	FREEMAN, TIM	EASA AD 2006-0345R1 PROP BLADE INSP	
06 Oct 2021 10:56	Event Added	FREEMAN, TIM	ANNUAL INSPECTION	
06 Oct 2021 10:56	Event Added	FREEMAN, TIM	200 HOUR INSPECTION AIRFRAME, PROPELLER AND ENGINE INSPECTION	
06 Oct 2021 10:56	Event Added	FREEMAN, TIM	FAA AD 2007-26-13 PROPELLER BLADES	
12 Oct 2021 11:11	Parts Posted	Watlington, Carlos		
12 Oct 2021 11:18	Part Filled	ALENAZI, NAFEL	(1) LN94-20020	
12 Oct 2021 11:27	Discrepancy Added	FREEMAN, TIM	COMPLY WITH ENGINE SERVICING AND ECU BATTERY REPLACEMENT TO ASSIST WITH ANNUAL INSPECTION REQUIREMENTS. CHANGE ENGINE OIL, CHANGE GEARBOX OIL, CHANGE AIR FILTER, CHANGE OIL FILTER, REPLACE 2 EACH ECU BATTERIES, COMPLY WITH LANDING GEAR WHEEL BEARING INSPECTION AND PACKING OF NEW GREASE.	
12 Oct 2021 15:16	Parts Posted	FREEMAN, TIM		
12 Oct 2021 15:17	Part Filled	FREEMAN, TIM	(8) 5W40 ENGINE OIL	
12 Oct 2021 15:17	Part Filled	FREEMAN, TIM	(1) E4A-52-000-KIT	
12 Oct 2021 15:17	Part Filled	FREEMAN, TIM	(1) RU-1620	
12 Oct 2021 15:17	Part Filled	FREEMAN, TIM	(1) WK724_3	
12 Oct 2021 15:18	Part Filled	FREEMAN, TIM	(1) E4A-70-000-806	
12 Oct 2021 15:19	Part Installed on Resource	FREEMAN, TIM	(1) LN94-20020	
12 Oct 2021 15:19	Part Installed on Resource	FREEMAN, TIM	(8) 5W40 ENGINE OIL	
12 Oct 2021 15:19	Part Installed on Resource	FREEMAN, TIM	(1) E4A-52-000-KIT	
12 Oct 2021 15:19	Part Installed on Resource	FREEMAN, TIM	(1) RU-1620	
12 Oct 2021 15:19	Part Installed on Resource	FREEMAN, TIM	(1) E4A-70-000-806	
12 Oct 2021 15:19	Part Installed on Resource	FREEMAN, TIM	(1) WK724_3	
12 Oct 2021 15:19	Closed	FREEMAN, TIM		

Work Order 2021 00519			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
06 Oct 2021 10:57	Opened	FREEMAN, TIM		
06 Oct 2021 10:57	Discrepancy Added	FREEMAN, TIM	COMPLY WITH ANNUAL INSPECTION FINDINGS REF. W/O 2021-00517	
13 Oct 2021 05:16	Parts Posted	GADZAMA, SAMUEL		
13 Oct 2021 05:19	Part Filled	GADZAMA, SAMUEL	(8) A3135-017-24A	
22 Oct 2021 11:14	Discrepancy Added	FREEMAN, TIM	L/H AND R/H ENG. SHOCK MOUNT RUBBER WITH CRACKS AND OIL LEAK.	
22 Oct 2021 11:14	Discrepancy Added	FREEMAN, TIM	ENGINE TURBO CHARGER WITH SIGN OF OIL LEAK AT LWR SECTION.	
22 Oct 2021 11:14	Discrepancy Added	FREEMAN, TIM	ELEV. TRIM IS JURKY AND NOISY.	
22 Oct 2021 11:15	Discrepancy Added	FREEMAN, TIM	HYD FLUID IS DRIPPING FROM BRAKE RESIRVOIR AT COPILOT SIDE.	
22 Oct 2021 11:15	Discrepancy Added	FREEMAN, TIM	F/EXT. AND FAK ARE EXPIRED.	
22 Oct 2021 11:15	Discrepancy Added	FREEMAN, TIM	AFT FUESLAGE AREA WITH DUST AROUND BATTER.	
29 Oct 2021 12:54	Discrepancy Added	FREEMAN, TIM	LANDING/TAXI LIGHT LENS COVER WASHERS CORRODED	
29 Oct 2021 12:54	Part Installed on Resource	FREEMAN, TIM	(8) A3135-017-24A	
29 Oct 2021 12:54	Closed	FREEMAN, TIM		

Work Order 2021 00520			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
06 Oct 2021 10:58	Opened	FREEMAN, TIM		
06 Oct 2021 10:58	Discrepancy Added	FREEMAN, TIM	COMPLY WITH POST ANNUAL MAINTENANCE TEST FLIGHT	
12 Oct 2021 15:40	Discrepancy Added	FREEMAN, TIM	COMPLY WITH COMPASS CALIBRATION AS REQUIRED PER ANNUAL INSPECTION REF WORK ORDER 2021-00518	
20 Dec 2021 02:58	Discrepancy Added	Watlington, Carlos	ECU BATTERIES REQUIRE REPLACEMENT.	
20 Dec 2021 03:01	Remove Discrepancy	Watlington, Carlos	NEED CORRECTION	
20 Dec 2021 03:01	Discrepancy Added	Watlington, Carlos	ECU BATTERIES REQUIRE REPLACEMENT.	
20 Dec 2021 03:22	Parts Posted	Watlington, Carlos		
20 Dec 2021 10:14	Part Filled	ALENAZI, NAFEL	(2) LC-R127R2PG	
21 Dec 2021 08:14	Parts Posted	MILIBARI, SULTAN		
21 Dec 2021 08:43	Part Filled	ALENAZI, NAFEL	(1) DIN3771-46.2X3.55	
22 Dec 2021 10:29	Event Added	FREEMAN, TIM	ECU BATTERY REPLACEMENT	
05 Jan 2022 12:23	Part Installed on Resource	FREEMAN, TIM	(2) LC-R127R2PG	
05 Jan 2022 12:23	Part Installed on Resource	FREEMAN, TIM	(1) DIN3771-46.2X3.55	
05 Jan 2022 12:23	Closed	FREEMAN, TIM		

Work Order 2021 00523			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
07 Oct 2021	09:27	Opened	FREEMAN, TIM			
07 Oct 2021	09:27	Discrepancy Added	FREEMAN, TIM		REMOVE NOSE AND MAIN WHEEL FAIRINGS FOR STORAGE	
12 Oct 2021	11:26	Closed	FREEMAN, TIM			

Work Order 2021 00558		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
21 Oct 2021 09:59	Opened	FREEMAN, TIM		
21 Oct 2021 09:59	Discrepancy Added	FREEMAN, TIM	TECH LOG REQUIRED FOR NEW AIRCRAFT	
21 Oct 2021 10:00	Closed	FREEMAN, TIM		

Work Order 2021 00570			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
21 Oct 2021	14:35	Opened	GADZAMA, SAMUEL			
21 Oct 2021	14:35	Event Added	GADZAMA, SAMUEL		AD EASA 2021-0203-E	
29 Oct 2021	12:57	Closed	FREEMAN, TIM			

Work Order 2021 00571			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
21 Oct 2021 15:10	Opened	GADZAMA, SAMUEL		
21 Oct 2021 15:10	Event Added	GADZAMA, SAMUEL	2021-17-01 OIL PUMP	
22 Oct 2021 06:12	Parts Posted	GADZAMA, SAMUEL		
22 Oct 2021 06:13	Part Filled	GADZAMA, SAMUEL	(15) PLT4SM30	
25 Oct 2021 11:06	Parts Posted	GADZAMA, SAMUEL		
26 Oct 2021 07:40	Part Filled	ALENAZI, NAFEL	(1) E4A-41-300-803	
28 Oct 2021 04:16	Parts Posted	GADZAMA, SAMUEL		
28 Oct 2021 06:44	Part Filled	ALENAZI, NAFEL	(10) PLT1MM30	
28 Oct 2021 06:44	Part Filled	ALENAZI, NAFEL	(10) PLT2SM30	
28 Oct 2021 11:52	Part Removed from Resource	GADZAMA, SAMUEL	(1) E4A-70-000-806	
28 Oct 2021 11:52	Parts Posted	GADZAMA, SAMUEL		
28 Oct 2021 11:53	Part Filled	GADZAMA, SAMUEL	(7) 5W40 ENGINE OIL	
28 Oct 2021 11:54	Part Filled	GADZAMA, SAMUEL	(2) SPIRAX-S6-GXME_20L	
28 Oct 2021 11:54	Part Filled	GADZAMA, SAMUEL	(1) E4A-70-000-806	
28 Oct 2021 13:46	Part Removed from Resource	GADZAMA, SAMUEL	(1) E4A-52-000-KIT	
28 Oct 2021 13:46	Parts Posted	GADZAMA, SAMUEL		
28 Oct 2021 13:56	Part Filled	ALENAZI, NAFEL	(1) E4A-50-000-000X serial # 00184	
28 Oct 2021 13:57	Part Filled	ALENAZI, NAFEL	(1) E4A-05-000-104	
28 Oct 2021 13:57	Part Filled	ALENAZI, NAFEL	(1) DIN7603-A12X16-AL	
28 Oct 2021 14:01	Parts Posted	ALENAZI, NAFEL		
28 Oct 2021 14:02	Part Filled	ALENAZI, NAFEL	(2) DIN7603-A12X16-AL	
28 Oct 2021 14:03	Part Filled	ALENAZI, NAFEL	(1) E4A-04-000-003	
28 Oct 2021 14:03	Part Filled	ALENAZI, NAFEL	(4) 2142110	
28 Oct 2021 14:03	Part Filled	ALENAZI, NAFEL	(1) OR_7.8X3.2-ACM70	
28 Oct 2021 14:03	Part Filled	ALENAZI, NAFEL	(1) DIN3771-16X3-ACM70	
28 Oct 2021 14:04	Part Filled	ALENAZI, NAFEL	(1) E4A-52-000-KIT	
28 Oct 2021 14:04	Part Filled	ALENAZI, NAFEL	(2) DIN7603-14X18X2.0	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(15) PLT4SM30	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(1) E4A-70-000-806	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(2) DIN7603-A12X16-AL	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(1) E4A-04-000-003	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(4) 2142110	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(1) OR_7.8X3.2-ACM70	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(1) DIN3771-16X3-ACM70	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(1) E4A-52-000-KIT	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(2) DIN7603-14X18X2.0	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(10) PLT1MM30	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(10) PLT2SM30	

Work Order		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(7) 5W40 ENGINE OIL	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(2) SPIRAX-S6-GXME_20L	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(1) E4A-50-000-000X serial # 00184	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(1) E4A-05-000-104	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(1) E4A-41-300-803	
29 Oct 2021 13:02	Part Installed on Resource	FREEMAN, TIM	(1) DIN7603-A12X16-AL	
29 Oct 2021 13:02	Closed	FREEMAN, TIM		

Work Order 2021 00583			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
28 Oct 2021 14:56	Opened	FREEMAN, TIM		
28 Oct 2021 14:56	Discrepancy Added	FREEMAN, TIM	REMOVE FIRST AID KIT CONTENTS, INSTALL FIRST AID KIT ITEMS PER GACA PART 91 APENDIX B. WITH QUALITY APPROVED MODIFICATION INDICATED ON INVENTORY LIST PLACED WITHIN THE FIRST AID KIT. INSTALL SAFETY SECURITY SEAL AND REGISTER TAG SERIAL NUMBER	
28 Oct 2021 15:04	Parts Posted	FREEMAN, TIM		
28 Oct 2021 15:13	Part Filled	FREEMAN, TIM	(1) TST-HC serial # HC-1822	
28 Oct 2021 15:28	Part Installed on Resource	FREEMAN, TIM	(1) TST-HC serial # HC-1822	
28 Oct 2021 15:28	Closed	FREEMAN, TIM		

Work Order 2021 00712			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
22 Dec 2021 11:30	Opened	Watlington, Carlos		
22 Dec 2021 11:30	Discrepancy Added	Watlington, Carlos	HPP LEAKING AT O-RING	
22 Dec 2021 11:47	Parts Posted	Watlington, Carlos		
22 Dec 2021 12:56	Part Filled	ALENAZI, NAFEL	(1) DIN3771-48X1,5	
22 Dec 2021 14:20	Part Removed from Work Order	ALENAZI, NAFEL	(1) DIN3771-48X1,5	
22 Dec 2021 14:33	Discrepancy Added	Watlington, Carlos	TURBOCHARGER LEAKING.	
22 Dec 2021 14:34	Parts Posted	Watlington, Carlos		
22 Dec 2021 14:43	Part Removed from Resource	Watlington, Carlos	(1) E4A-00-410-BHY serial # WA5003947100053	
22 Dec 2021 14:43	Parts Posted	Watlington, Carlos		
22 Dec 2021 14:46	Part Filled	ALENAZI, NAFEL	(1) E4A-00-410-BHY serial # WJ5004456100071	
23 Dec 2021 06:33	Discrepancy Added	Watlington, Carlos	ENGINE MOUNT WORN BEYOND LIMITS.	
23 Dec 2021 06:42	Parts Posted	Watlington, Carlos		
23 Dec 2021 08:52	Part Filled	ALENAZI, NAFEL	(1) D64-7126-14-71_01	
29 Dec 2021 14:04	Part Installed on Resource	Watlington, Carlos	(1) E4A-00-410-BHY serial # WJ5004456100071	
29 Dec 2021 14:04	Part Installed on Resource	Watlington, Carlos	(1) D64-7126-14-71_01	
29 Dec 2021 14:04	Closed	Watlington, Carlos		

Work Order		2022 00047		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
19 Jan 2022	12:46	Opened		FREEMAN, TIM			
19 Jan 2022	12:46	Discrepancy Added		FREEMAN, TIM		ETA squawk: "Flaps" not retracting, keep getting stuck on T/O or Landing.	
19 Jan 2022	20:10	Closed		FREEMAN, TIM			

Work Order 2022 00053			Work Order Status: Closed		Resource: XF-35	
When	Action		Who	Details		
23 Jan 2022 10:32	Opened		FREEMAN, TIM			
23 Jan 2022 10:32	Discrepancy Added		FREEMAN, TIM	STUDENT REGULARLY OVERSPEEDED FLAPS BY 1-3 KNOTS IN TO SETTING (REPORTED BY CREW)		
23 Jan 2022 12:23	Closed		PEREZ, Javier			
23 Jan 2022 14:19	Closed		PEREZ, Javier			

Work Order		2022 00055		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
25 Jan 2022	12:07	Opened		FREEMAN, TIM			
25 Jan 2022	12:07	Discrepancy Added		FREEMAN, TIM		HEADLINDER DISBONDING	
26 Jan 2022	09:42	Closed		FREEMAN, TIM			

Work Order 2022 00060			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
30 Jan 2022 10:02	Opened	PEREZ, Javier		
30 Jan 2022 10:02	Discrepancy Added	PEREZ, Javier	ETA squawk: Flap malfunction . Got stuck on T/O flap	
30 Jan 2022 10:03	Parts Posted	PEREZ, Javier		
30 Jan 2022 10:07	Parts Posted	PEREZ, Javier		
31 Jan 2022 05:22	Part Filled	ALENAZI, NAFEL	(1) DAI-9052-00-02	
02 Feb 2022 12:08	Parts Posted	PEREZ, Javier		
02 Feb 2022 12:10	Part Filled	PEREZ, Javier	(15) PLT2SM76	
02 Feb 2022 12:10	Part Filled	PEREZ, Javier	(18) PLT1MM30	
02 Feb 2022 12:51	Part Installed on Resource	PEREZ, Javier	(1) DAI-9052-00-02	
02 Feb 2022 12:51	Part Installed on Resource	PEREZ, Javier	(15) PLT2SM76	
02 Feb 2022 12:51	Part Installed on Resource	PEREZ, Javier	(18) PLT1MM30	
02 Feb 2022 12:51	Closed	PEREZ, Javier		
02 Feb 2022 13:17	Part Removed from Closed Work	ALENAZI, NAFEL	(1) DAI-9052-00-02	

Work Order 2022 00105			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
13 Feb 2022	14:09	Opened	PEREZ, Javier			
13 Feb 2022	14:09	Discrepancy Added	PEREZ, Javier		ETA squawk: Camera is not recording.	
13 Feb 2022	14:11	Closed	PEREZ, Javier			

Work Order		2022 00229		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
26 Mar 2022	05:10	Opened		GADZAMA, SAMUEL			
26 Mar 2022	05:10	Discrepancy Added		GADZAMA, SAMUEL		ETA squawk: oil leak in co pilot	
05 Apr 2022	06:45	Work Item Sign Off Reset		FREEMAN, TIM			
05 Apr 2022	11:56	Closed		Watlington, Carlos			

Work Order 2022 00249		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
29 Mar 2022 12:40	Opened	Watlington, Carlos		
29 Mar 2022 12:40	Discrepancy Added	Watlington, Carlos	FAK REQUIRES NEW SAFETY SEAL DUE TO INCLUSION OF SURVIVAL KIT.	
29 Mar 2022 12:40	Part Removed from Resource	Watlington, Carlos	(1) TST-HC serial # HC-1822	
29 Mar 2022 12:40	Parts Posted	Watlington, Carlos		
29 Mar 2022 13:46	Part Filled	ALENAZI, NAFEL	(1) TST-HC serial # HC-1895	
29 Mar 2022 14:03	Part Installed on Resource	Watlington, Carlos	(1) TST-HC serial # HC-1895	
29 Mar 2022 14:03	Closed	Watlington, Carlos		

Work Order	2022 00320	Work Order Status: Closed		Resource: XF-35
When	Action	Who		Details
26 Apr 2022 06:30	Opened	FREEMAN, TIM		
26 Apr 2022 06:30	Event Added	FREEMAN, TIM		100 HOUR AIRFRAME, PROPELLER AND ENGINE INSPECTION
26 Apr 2022 06:30	Event Added	FREEMAN, TIM		EASA AD 2006-0345R1 PROP BLADE INSP
26 Apr 2022 06:30	Event Added	FREEMAN, TIM		FAA AD 2007-26-13 PROPELLER BLADES
26 Apr 2022 06:31	Part Removed from Resource	FREEMAN, TIM		(1) E4A-52-000-KIT
26 Apr 2022 06:31	Parts Posted	FREEMAN, TIM		
26 Apr 2022 10:46	Part Filled	ALENAZI, NAFEL		(7) 5W40 ENGINE OIL
26 Apr 2022 10:47	Part Filled	ALENAZI, NAFEL		(1) RU-1620
26 Apr 2022 10:47	Part Filled	ALENAZI, NAFEL		(1) WK724_3
26 Apr 2022 10:47	Part Filled	ALENAZI, NAFEL		(1) E4A-52-000-KIT
26 Apr 2022 12:18	Parts Posted	FREEMAN, TIM		
26 Apr 2022 12:19	Part Filled	ALENAZI, NAFEL		(1) RSGU1.22_15
26 Apr 2022 12:27	Part Removed from Resource	FREEMAN, TIM		(1) TST-HC serial # HC-1895
26 Apr 2022 12:27	Parts Posted	FREEMAN, TIM		
26 Apr 2022 12:32	Part Filled	ALENAZI, NAFEL		(1) TST-HC serial # HC-1829
26 Apr 2022 14:46	Part Installed on Resource	FREEMAN, TIM		(1) TST-HC serial # HC-1829
26 Apr 2022 14:46	Part Installed on Resource	FREEMAN, TIM		(7) 5W40 ENGINE OIL
26 Apr 2022 14:46	Part Installed on Resource	FREEMAN, TIM		(1) RU-1620
26 Apr 2022 14:46	Part Installed on Resource	FREEMAN, TIM		(1) WK724_3
26 Apr 2022 14:46	Part Installed on Resource	FREEMAN, TIM		(1) E4A-52-000-KIT
26 Apr 2022 14:46	Part Installed on Resource	FREEMAN, TIM		(1) RSGU1.22_15
26 Apr 2022 14:46	Closed	FREEMAN, TIM		
27 Apr 2022 06:00	Closed	Watlington, Carlos		
17 Sep 2022 06:27	Parts Posted	PEREZ, Javier		
17 Sep 2022 06:53	Part Filled	PEREZ, Javier		(1) E4A-70-000-806
17 Sep 2022 06:53	Part Installed on Resource	PEREZ, Javier		(1) E4A-70-000-806

Work Order 2022 00321			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
27 Apr 2022	05:07	Opened	FREEMAN, TIM		PROP TRAILING EDGE MINOR DAMAGE DUE TO AIR DUCT CONTACT DURING ENGINE OPERATION.	
27 Apr 2022	05:07	Discrepancy Added	FREEMAN, TIM			
27 Apr 2022	05:43	Closed	Watlington, Carlos			
27 Apr 2022	06:03	Closed	Watlington, Carlos			

Work Order 2022 00334		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
09 May 2022 06:38	Opened	GADZAMA, SAMUEL		
09 May 2022 06:38	Discrepancy Added	GADZAMA, SAMUEL	PILOT REPORTED MAIN BATTERY FLAT.	
09 May 2022 06:59	Closed	FREEMAN, TIM		
09 May 2022 08:54	Parts Posted	GADZAMA, SAMUEL		
09 May 2022 10:41	Part Filled	ALENAZI, NAFEL	(1) RG24-15 serial # 40907337	
09 May 2022 10:41	Part Installed on Resource	ALENAZI, NAFEL	(1) RG24-15 serial # 40907337	
09 May 2022 10:45	Part Removed from Closed Work	ALENAZI, NAFEL	(1) RG24-15 serial # 40907337	
09 May 2022 10:46	Parts Posted	ALENAZI, NAFEL		
09 May 2022 10:47	Part Filled	ALENAZI, NAFEL	(1) RG24-15 serial # 40907337	
09 May 2022 10:47	Part Installed on Resource	ALENAZI, NAFEL	(1) RG24-15 serial # 40907337	

Work Order		2022 00340		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
10 May 2022	14:38	Opened		GADZAMA, SAMUEL			
10 May 2022	14:38	Discrepancy Added		GADZAMA, SAMUEL		ETA squawk: ECU failure	
10 May 2022	14:42	Closed		GADZAMA, SAMUEL			

Work Order 2022 00362		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
20 May 2022 08:07	Opened	Watlington, Carlos		
20 May 2022 08:07	Discrepancy Added	Watlington, Carlos	CREW REPORTED RADIO MALFUNCTION. TRANSMISSION IS POOR BOTH COM 1-2 READABILITY REPORTED 1 BY 5	
21 May 2022 12:01	Closed	Watlington, Carlos		

Work Order 2022 00378		Work Order Status: Closed		Resource: XF-35	
When	Action	Who		Details	
27 May 2022 04:25	Opened	PEREZ, Javier			
27 May 2022 04:25	Discrepancy Added	PEREZ, Javier		ETA squawk: Oil leak R-side of cowling during post-flight inspection of student 1, cowling cleaned, oil quantity verified full. leak was discovered again at end of student 2 flight.	
27 May 2022 12:47	Closed	Watlington, Carlos			

Work Order 2022 00470			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
24 Jun 2022	06:12	Opened	PEREZ, Javier			
24 Jun 2022	06:12	Discrepancy Added	PEREZ, Javier		REMOVE SUNVISORS FOR STORAGE	
24 Jun 2022	06:13	Closed	PEREZ, Javier			

Work Order		2022 00475		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
25 Jun 2022	04:08	Opened		Watlington, Carlos			
25 Jun 2022	04:08	Discrepancy Added		Watlington, Carlos		ETA squawk: Trim wheel, Overhead console	
25 Jun 2022	08:31	Closed		Watlington, Carlos			

Work Order 2022 00477			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
25 Jun 2022	11:09	Opened	Watlington, Carlos			
25 Jun 2022	11:09	Discrepancy Added	Watlington, Carlos		TECH LOG FULL	
25 Jun 2022	11:22	Closed	Watlington, Carlos			

Work Order 2022 00523			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
26 Jul 2022 07:34	Opened	GADZAMA, SAMUEL		
26 Jul 2022 07:34	Discrepancy Added	GADZAMA, SAMUEL	ETA squawk: Red X on altimeter type and TAS. Yellow X on VSI. X's would come and go periodically. Transponder was also periodically not reporting in mode C	
26 Jul 2022 09:46	Closed	GADZAMA, SAMUEL		

Work Order 2022 00526		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
29 Jul 2022 10:46	Opened	Watlington, Carlos		
29 Jul 2022 10:46	Discrepancy Added	Watlington, Carlos	ETA squawk: Instrument error + suspected leak prop hub	
29 Jul 2022 11:14	Closed	Watlington, Carlos		
29 Jul 2022 11:36	Work Item Sign Off Reset	Watlington, Carlos		
29 Jul 2022 11:39	Closed	Watlington, Carlos		

Work Order		2022 00527		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
29 Jul 2022	11:41	Opened		Watlington, Carlos			
29 Jul 2022	11:41	Discrepancy Added		Watlington, Carlos		CREW REPORTED SUBSTANTIAL OIL RESIDUE ON PROP IN POST FLIGHT INSPECTION. FORE AND BACK COVERED, ALL THREE BLADES.	
29 Jul 2022	11:48	Closed		Watlington, Carlos			

Work Order 2022 00531			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
02 Aug 2022 09:08	Opened	GADZAMA, SAMUEL		
02 Aug 2022 09:08	Discrepancy Added	GADZAMA, SAMUEL	RH STEP MISSING ANTI SLIP TAPE.	
02 Aug 2022 09:14	Parts Posted	GADZAMA, SAMUEL		
02 Aug 2022 09:20	Part Filled	ALKHRAISI, ABDULLAH	(1) DA4-5300-62-04_2	
02 Aug 2022 11:52	Part Installed on Resource	GADZAMA, SAMUEL	(1) DA4-5300-62-04_2	
02 Aug 2022 11:52	Closed	GADZAMA, SAMUEL		

Work Order 2022 00558		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
11 Aug 2022 06:18	Opened	ALKHRAISI, ABDULLAH		
11 Aug 2022 06:18	Discrepancy Added	ALKHRAISI, ABDULLAH	ETA squawk: TAS, OAT, ALT, VSI Inop intermittently	
18 Aug 2022 11:13	Closed	FREEMAN, TIM		
18 Aug 2022 11:14	Work Item Sign Off Reset	FREEMAN, TIM		
18 Aug 2022 11:16	Discrepancy Added	FREEMAN, TIM	COMPLY WITH DEFECT 1	

Work Order 2022 00573			Work Order Status: Closed	Resource: XF-35
When	Action		Who	Details
18 Aug 2022 11:17	Opened		FREEMAN, TIM	
18 Aug 2022 11:17	Discrepancy Added		FREEMAN, TIM	ETA squawk: TAS, OAT, ALT, VSI Inop intermittently
01 Sep 2022 11:01	Closed		PEREZ, Javier	
15 Sep 2022 13:28	Work Item Sign Off Reset		PEREZ, Javier	
15 Sep 2022 13:34	Work Item Sign Off Reset		PEREZ, Javier	

Work Order		2022 00613		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
29 Aug 2022	13:25	Opened		GADZAMA, SAMUEL			
29 Aug 2022	13:25	Event Added		GADZAMA, SAMUEL		MSB 40NG-078	
29 Aug 2022	13:33	Closed		GADZAMA, SAMUEL			

Work Order		2022 00637	Work Order Status: Closed		Resource: XF-35	
When		Action		Who	Details	
02 Sep 2022	10:51	Opened		Watlington, Carlos		
02 Sep 2022	10:51	Discrepancy Added		Watlington, Carlos	CREW REPORTED LOSS OF GARMIN VERT SPEED, TRUE SPEED, ALT AND OAT	
03 Sep 2022	07:13	Closed		PEREZ, Javier		
03 Sep 2022	10:50	Work Item Sign Off Reset		PEREZ, Javier		
03 Sep 2022	10:50	Work Item Sign Off Reset		PEREZ, Javier		

Work Order 2022 00667			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
16 Sep 2022 12:02	Opened	PEREZ, Javier		
16 Sep 2022 12:02	Event Added	PEREZ, Javier	ANNUAL INSPECTION	
16 Sep 2022 12:03	Event Added	PEREZ, Javier	FIRE EXTINGUISHER ANNUAL INSPECTION AMEREX	
16 Sep 2022 12:03	Event Added	PEREZ, Javier	200 HOUR INSPECTION AIRFRAME, PROPELLER AND ENGINE INSPECTION	
16 Sep 2022 12:03	Event Added	PEREZ, Javier	FAA AD 2007-26-13 PROPELLER BLADES	
16 Sep 2022 12:03	Event Added	PEREZ, Javier	EASA AD 2006-0345R1 PROP BLADE INSP	
16 Sep 2022 12:04	Event Added	PEREZ, Javier	200 HOUR FDR INSPECTION	
16 Sep 2022 12:04	Event Added	PEREZ, Javier	100 HOUR AIRFRAME, PROPELLER AND ENGINE INSPECTION	
16 Sep 2022 12:04	Event Added	PEREZ, Javier	AUTOPILOT GFC700 MECHANICAL CHECK	
16 Sep 2022 12:04	Event Added	PEREZ, Javier	FIRST AID KIT INSPECTION	
16 Sep 2022 12:18	Event Added	PEREZ, Javier	RACC SYSTEM	
16 Sep 2022 12:53	Event Added	PEREZ, Javier	EMERGENCY BATTERY	
17 Sep 2022 05:28	Event Added	PEREZ, Javier	ELT FUNCTION TEST	
17 Sep 2022 05:34	Part Removed from Resource	AL HAZMI, FAISAL	(1) E4A-52-000-KIT	
17 Sep 2022 05:34	Parts Posted	AL HAZMI, FAISAL		
17 Sep 2022 06:56	Part Filled	PEREZ, Javier	(7) 5W40 ENGINE OIL	
17 Sep 2022 06:56	Part Filled	PEREZ, Javier	(1) WK724_3	
17 Sep 2022 06:56	Part Filled	PEREZ, Javier	(1) RU-1620	
17 Sep 2022 07:02	Part Filled	PEREZ, Javier	(1) E4A-52-000-KIT	
17 Sep 2022 12:05	Parts Posted	Ibrahim, ABDULLAH		
17 Sep 2022 12:09	Part Filled	ALENAZI, NAFEL	(1) LN94-20020	
17 Sep 2022 13:22	Part Removed from Resource	PEREZ, Javier	(1) TST-HC serial # HC-1829	
17 Sep 2022 13:22	Parts Posted	PEREZ, Javier		
17 Sep 2022 13:25	Part Filled	ALENAZI, NAFEL	(1) TST-HC serial # HC-1833	
18 Sep 2022 04:20	Event Added	PEREZ, Javier	ECU BATTERY REPLACEMENT	
18 Sep 2022 04:20	Parts Posted	PEREZ, Javier		
18 Sep 2022 05:06	Part Filled	PEREZ, Javier	(2) LC-R127R2PG	
18 Sep 2022 09:17	Parts Posted	Ibrahim, ABDULLAH		
19 Sep 2022 06:28	Part Filled	ALENAZI, NAFEL	(20) PLT4SM30	
19 Sep 2022 10:45	Parts Posted	AL IBRAHIM, IBRAHIM		
19 Sep 2022 13:25	Part Filled	ALENAZI, NAFEL	(1) ORO375	
20 Sep 2022 04:05	Part Removed from Resource	GADZAMA, SAMUEL	(1) D60-2560-91-00	
20 Sep 2022 04:05	Parts Posted	GADZAMA, SAMUEL		
20 Sep 2022 09:50	Part Filled	ALENAZI, NAFEL	(1) D60-2560-91-00	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(1) ORO375	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(7) 5W40 ENGINE OIL	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(1) WK724_3	

Work Order		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(1) RU-1620	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(1) LN94-20020	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(1) TST-HC serial # HC-1833	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(1) E4A-52-000-KIT	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(20) PLT4SM30	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(1) D60-2560-91-00	
20 Sep 2022 16:06	Part Installed on Resource	GADZAMA, SAMUEL	(2) LC-R127R2PG	
20 Sep 2022 16:06	Closed	GADZAMA, SAMUEL		

Work Order 2022 00668		Work Order Status: Cancelled		Resource: XF-35
When	Action	Who	Details	
16 Sep 2022 12:03	Opened	PEREZ, Javier		
16 Sep 2022 12:03	Event Added	PEREZ, Javier	MSB 40NG-077	
16 Sep 2022 12:52	Remove Event	PEREZ, Javier	NEED CORRECTION	
16 Sep 2022 12:52	Cancelled	PEREZ, Javier	NEED CORRECTION	

Work Order 2022 00669			Work Order Status: Closed		Resource: XF-35	
When	Action		Who		Details	
16 Sep 2022 12:03	Opened		PEREZ, Javier			
16 Sep 2022 12:03	Event Added		PEREZ, Javier		MAGNETIC COMPASS	
16 Sep 2022 12:05	Discrepancy Added		PEREZ, Javier		POST ANNUAL INSPECTION TEST FLIGHT REQUIRED	
22 Jan 2023 06:30	Remove Event		PEREZ, Javier		NEED CORRECTION	
23 Jan 2023 16:18	Closed		ALkhraissi, Abdulrhman			

Work Order 2022 00670			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
16 Sep 2022 12:05	Opened	PEREZ, Javier		
16 Sep 2022 12:05	Discrepancy Added	PEREZ, Javier	ANNUAL INSPECTION FINDINGS	
20 Sep 2022 14:06	Discrepancy Added	GADZAMA, SAMUEL	FUEL FILTER BOWL DRAIN PLUG NOT SAFETY WIRED.	
20 Sep 2022 14:09	Discrepancy Added	GADZAMA, SAMUEL	TAXI LIGHT LENS DIRTY INNER SIDE.	
20 Sep 2022 14:10	Discrepancy Added	GADZAMA, SAMUEL	TIE STRAP FALLEN BEHIND INSTRUMENT PANEL R/H SIDE.	
20 Sep 2022 14:11	Discrepancy Added	GADZAMA, SAMUEL	L/H PASSENGER SEATS COVER RAIL LOOSE.	
20 Sep 2022 15:52	Discrepancy Added	GADZAMA, SAMUEL	INSTALL AND FUNCTION CHECK RACC POST ANNUAL INSPECTION.	
25 Sep 2022 08:32	Discrepancy Added	PEREZ, Javier	WALKWAY PLACARDS FADED	
25 Sep 2022 08:32	Parts Posted	PEREZ, Javier		
25 Sep 2022 08:39	Part Filled	ALENAZI, NAFEL	(3) DA4-1123-10-11	
26 Sep 2022 09:23	Discrepancy Added	PEREZ, Javier	LANDING LIGHT COVER RIV NUT MISSING UNDER THE WING	
29 Sep 2022 11:14	Discrepancy Added	GADZAMA, SAMUEL	LH FWD ENG MOUNTS LEAKING.	
01 Dec 2022 05:54	Parts Posted	FREEMAN, TIM		
01 Dec 2022 07:16	Part Filled	GADZAMA, SAMUEL	(1) D64-7126-14-70_01	
02 Dec 2022 13:37	Parts Posted	ALZUBAIDI, EYAD		
03 Dec 2022 07:58	Part Filled	ALENAZI, NAFEL	(1) D64-7126-14-70_01	
04 Dec 2022 07:18	Part Removed from Work Order	ALENAZI, NAFEL	(1) D64-7126-14-70_01	
06 Dec 2022 08:47	Part Installed on Resource	GADZAMA, SAMUEL	(1) D64-7126-14-70_01	
06 Dec 2022 08:47	Part Installed on Resource	GADZAMA, SAMUEL	(3) DA4-1123-10-11	
06 Dec 2022 08:47	Closed	GADZAMA, SAMUEL		

Work Order 2022 00671		Work Order Status: Closed		Resource: XF-35	
When		Action	Who	Details	
16 Sep 2022	12:18	Opened	PEREZ, Javier		
16 Sep 2022	12:18	Event Added	PEREZ, Javier	ATTENUATORS	
17 Sep 2022	12:04	Closed	PEREZ, Javier		
17 Sep 2022	12:51	Work Item Sign Off Reset	PEREZ, Javier		

Work Order		2022 00674		Work Order Status: Cancelled		Resource: XF-35	
When		Action		Who		Details	
17 Sep 2022	05:27	Opened		PEREZ, Javier			
17 Sep 2022	05:27	Event Added		PEREZ, Javier		ELT FUNCTION TEST	
17 Sep 2022	05:27	Remove Event		PEREZ, Javier		NEED CORRECTION	
17 Sep 2022	05:27	Cancelled		PEREZ, Javier		NEED CORRECTION	

Work Order 2022 00677		Work Order Status: Cancelled		Resource: XF-35
When	Action	Who	Details	
18 Sep 2022 04:18	Opened	PEREZ, Javier		
18 Sep 2022 04:18	Event Added	PEREZ, Javier	ECU BATTERY REPLACEMENT	
18 Sep 2022 04:19	Remove Event	PEREZ, Javier	NEED CORRECTION	
18 Sep 2022 04:19	Cancelled	PEREZ, Javier	NEED CORRECTION	

Work Order 2022 00705			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
30 Sep 2022 04:58	Opened	PEREZ, Javier		
30 Sep 2022 04:58	Event Added	PEREZ, Javier	GACA 91.451 ALTIMETER REPORTING CHECK	
04 Oct 2022 11:56	Event Added	FREEMAN, TIM	GACA 91.453, ATC TRANSPONDER 24 MONTH	
04 Oct 2022 11:56	Event Added	FREEMAN, TIM	PITOT STATIC SYSTEM TEST,1000 HOUR	
04 Oct 2022 12:09	Event Added	FREEMAN, TIM	GACA 91.453, TRANSPONDER REPORTING, 1000 HOUR	
04 Oct 2022 12:22	Remove Event	FREEMAN, TIM	NEED CORRECTION	
04 Oct 2022 12:24	Event Added	FREEMAN, TIM	PITOT STATIC SYSTEM 24 MONTH	
10 Oct 2022 05:51	Closed	ALkhraissi, Abdulrhman		
10 Oct 2022 10:08	Work Item Sign Off Reset	MEDINA, ROOSBER		
10 Oct 2022 10:09	Work Item Sign Off Reset	MEDINA, ROOSBER		
10 Oct 2022 10:09	Work Item Sign Off Reset	MEDINA, ROOSBER		
10 Oct 2022 10:09	Work Item Sign Off Reset	MEDINA, ROOSBER		
10 Oct 2022 10:09	Work Item Sign Off Reset	MEDINA, ROOSBER		

Work Order		2022 00721		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
05 Oct 2022	05:30	Opened		FREEMAN, TIM			
05 Oct 2022	05:30	Discrepancy Added		FREEMAN, TIM		INSTALL AND SECURE PILOT SEAT AND CARGO COMPARTMENT PANELLING POST 24 CALENDAR MONTH INSPECTION	
06 Oct 2022	13:18	Work Item Sign Off Reset		Al MOHAISEN, Muayed			
10 Oct 2022	06:12	Closed		ALkhraissi, Abdulrhman			

Work Order		2022 00757		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
17 Oct 2022	13:40	Opened		ALkhraissi, Abdulrhman			
17 Oct 2022	13:40	Discrepancy Added		ALkhraissi, Abdulrhman		COMPLY WITH 30 DAY ENGINE RUNS DUE TO GROUNDED FLEET.	
17 Oct 2022	14:12	Closed		ALkhraissi, Abdulrhman			

Work Order 2022 00878			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
22 Nov 2022 08:41	Opened	GADZAMA, SAMUEL		
22 Nov 2022 08:41	Event Added	GADZAMA, SAMUEL	MSB 40NG-077	
22 Nov 2022 08:42	Parts Posted	GADZAMA, SAMUEL		
22 Nov 2022 10:28	Part Filled	ALENAZI, NAFEL	(1) D64-1126-20-27	
29 Nov 2022 09:02	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) D64-1126-20-27	
29 Nov 2022 09:02	Closed	ALkhraissi, Abdulrhman		

Work Order 2022 00926			Work Order Status: Closed	Resource: XF-35
When	Action		Who	Details
29 Nov 2022 07:57	Opened		MEDINA, ROOSBER	
29 Nov 2022 07:57	Event Added		MEDINA, ROOSBER	MSB 40NG-065 REV. 1
05 Dec 2022 14:04	Work Item Sign Off Reset		GADZAMA, SAMUEL	
05 Dec 2022 14:05	Closed		GADZAMA, SAMUEL	
05 Dec 2022 14:05	Closed		GADZAMA, SAMUEL	

Work Order 2022 00927			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
29 Nov 2022 07:58	Opened	MEDINA, ROOSBER		
29 Nov 2022 07:58	Event Added	MEDINA, ROOSBER	MSB 40NG-070 REV0 ENGINE SAFETY ROPES INSP	
04 Dec 2022 07:59	Parts Posted	ALZUBAIDI, EYAD		
04 Dec 2022 08:00	Parts Posted	ALZUBAIDI, EYAD		
04 Dec 2022 08:00	Part Filled	ALENAZI, NAFEL	(4) PLT2SM76	
04 Dec 2022 08:01	Part Filled	ALENAZI, NAFEL	(1) CR2-M	
04 Dec 2022 09:07	Work Item Sign Off Reset	ALZUBAIDI, EYAD		
04 Dec 2022 14:13	Part Installed on Resource	Watlington, Carlos	(1) CR2-M	
04 Dec 2022 14:13	Part Installed on Resource	Watlington, Carlos	(4) PLT2SM76	
04 Dec 2022 14:13	Closed	Watlington, Carlos		

Work Order 2022 00928		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
29 Nov 2022 07:58	Opened	MEDINA, ROOSBER		
29 Nov 2022 07:58	Event Added	MEDINA, ROOSBER	MSB40NG-002 REV 17 Software for E4-A (AE300) Engine	
01 Dec 2022 07:18	Closed	ALkhraissi, Abdulrhman		

Work Order 2022 00947			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
29 Nov 2022	09:21	Opened	MEDINA, ROOSBER			
29 Nov 2022	09:21	Event Added	MEDINA, ROOSBER		MSB 40NG-078 REV 1 RUDDER CABLE INSPECTION	
01 Dec 2022	07:20	Closed	ALkhraissi, Abdulrhman			

Work Order 2022 00958			Work Order Status: Closed		Resource: XF-35	
When	Action		Who	Details		
29 Nov 2022 11:35	Opened		MEDINA, ROOSBER			
29 Nov 2022 11:35	Event Added		MEDINA, ROOSBER	MSB 40NG-003 R14 SOFTWARE GARMIN G1000; APPROVED SOFTWARE SYS.		
04 Dec 2022 14:00	Closed		PEREZ, Javier			

Work Order 2022 00975			Work Order Status: Closed		Resource: XF-35	
When	Action		Who	Details		
01 Dec 2022 14:22	Opened		MEDINA, ROOSBER			
01 Dec 2022 14:22	Event Added		MEDINA, ROOSBER	MSB-E4-003/27 SOFTWARE AND HARDWARE VERSIONS OF THE E4 ENGINE S		
05 Dec 2022 06:18	Closed		GADZAMA, SAMUEL			
05 Dec 2022 06:18	Closed		GADZAMA, SAMUEL			

Work Order 2022 00999			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
06 Dec 2022 08:37	Opened	GADZAMA, SAMUEL		
06 Dec 2022 08:37	Discrepancy Added	GADZAMA, SAMUEL	LANDING LIGHT COVER RIV NUT MISSING UNDER THE WING.	
16 Jan 2023 07:28	Parts Posted	GADZAMA, SAMUEL		
16 Jan 2023 07:30	Part Filled	ALENAZI, NAFEL	(1) UM-4-R	
16 Jan 2023 08:35	Parts Posted	AL IBRAHIM, IBRAHIM		
16 Jan 2023 08:37	Part Filled	ALENAZI, NAFEL	(1) DIN965-M4X20-A2	
17 Jan 2023 04:49	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) UM-4-R	
17 Jan 2023 04:49	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) DIN965-M4X20-A2	
17 Jan 2023 04:49	Closed	ALkhraissi, Abdulrhman		

Work Order 2022 01052		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
22 Dec 2022 07:27	Opened	MILIBARI, SULTAN		
22 Dec 2022 07:27	Discrepancy Added	MILIBARI, SULTAN	FIRST AID KIT INSPECTION SANITARY WIPE EXPIRATION	
22 Dec 2022 08:15	Part Removed from Resource	MILIBARI, SULTAN	(1) TST-HC serial # HC-1833	
22 Dec 2022 08:15	Parts Posted	MILIBARI, SULTAN		
22 Dec 2022 09:50	Parts Posted	Ibrahim, ABDULLAH		
22 Dec 2022 13:19	Part Filled	MILIBARI, SULTAN	(1) DETTOL-W1402	
22 Dec 2022 13:20	Part Filled	MILIBARI, SULTAN	(1) TST-HC serial # HC-1876	
23 Dec 2022 05:57	Event Added	PEREZ, Javier	FIRST AID KIT INSPECTION	
24 Dec 2022 06:45	Part Installed on Resource	PEREZ, Javier	(1) DETTOL-W1402	
24 Dec 2022 06:45	Part Installed on Resource	PEREZ, Javier	(1) TST-HC serial # HC-1876	
24 Dec 2022 06:45	Closed	PEREZ, Javier		

Work Order 2023 00086		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
22 Jan 2023 06:30	Opened	PEREZ, Javier		
22 Jan 2023 06:30	Event Added	PEREZ, Javier	MAGNETIC COMPASS	
22 Jan 2023 14:23	Discrepancy Added	ALZUBAIDI, EYAD	DURING COMPASS CHECK COMPASS COEFIENT B ADJUSMENT SCREW FOUND BROKEN	
22 Jan 2023 14:47	Part Removed from Resource	AL HAZMI, FAISAL	(1) PG2C-28V	
22 Jan 2023 14:47	Parts Posted	AL HAZMI, FAISAL		
23 Jan 2023 16:11	Work Item Sign Off Reset	ALkhraissi, Abdulrhman		
23 Jan 2023 16:16	Closed	ALkhraissi, Abdulrhman		

Work Order 2023 00194			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
06 Feb 2023	08:43	Opened	MEDINA, ROOSBER			
06 Feb 2023	08:43	Event Added	MEDINA, ROOSBER		RSB 40NG-076 UPPER COWLING AIR DUCT MODIFICATION	
06 Feb 2023	09:11	Closed	MEDINA, ROOSBER			

Work Order 2023 00195			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
06 Feb 2023	08:43	Opened	MEDINA, ROOSBER			
06 Feb 2023	08:43	Event Added	MEDINA, ROOSBER		FAA AD 2022-13-06	
06 Feb 2023	09:18	Closed	MEDINA, ROOSBER			

Work Order 2023 00211			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
07 Feb 2023 13:06	Opened	MEDINA, ROOSBER		
07 Feb 2023 13:06	Discrepancy Added	MEDINA, ROOSBER	OSB40NG-069 INSTALLATION OF GARMIN FLIGHT STREAM (FS510)	
07 Feb 2023 13:06	Discrepancy Added	MEDINA, ROOSBER	OSB40NG-071 INSTALLATION OF STAINLESS STEEL UNDERBELLY FIRE PROTECTION	
07 Feb 2023 13:06	Discrepancy Added	MEDINA, ROOSBER	OSB40NG-072 INSTALLATION OF ALTERNATE COOLANT TANK D44-7521-00-00_3	
07 Feb 2023 13:07	Discrepancy Added	MEDINA, ROOSBER	OSB40NG-073 INSTALLATION OF REDESIGNED MAP LIGHTS	
07 Feb 2023 13:07	Discrepancy Added	MEDINA, ROOSBER	OSB40NG-074 INSTALLATION OF A BUBBLE CANNOPY	
07 Feb 2023 13:13	Closed	MEDINA, ROOSBER		

Work Order 2023 00223			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
08 Feb 2023	14:30	Opened	GADZAMA, SAMUEL			
08 Feb 2023	14:30	Discrepancy Added	GADZAMA, SAMUEL		PILOT REPORTED RACC ASSY U/S.	
08 Feb 2023	14:52	Closed	MEDINA, ROOSBER			

Work Order 2023 00226		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
10 Feb 2023 05:02	Opened	MILIBARI, SULTAN		
10 Feb 2023 05:02	Discrepancy Added	MILIBARI, SULTAN	ETA squawk: RACC Inop	
10 Feb 2023 12:32	Parts Posted	PEREZ, Javier		
10 Feb 2023 14:39	Parts Posted	PEREZ, Javier		
10 Feb 2023 14:40	Part Filled	PEREZ, Javier	(2) LC-R121R3P_	
10 Feb 2023 14:45	Work Item Sign Off Reset	PEREZ, Javier		
10 Feb 2023 14:47	Part Filled	PEREZ, Javier	(1) D64-2416-30-00-01 serial # H-U022336	
10 Feb 2023 14:50	Part Installed on Resource	PEREZ, Javier	(2) LC-R121R3P_	
10 Feb 2023 14:50	Part Installed on Resource	PEREZ, Javier	(1) D64-2416-30-00-01 serial # H-U022336	
10 Feb 2023 14:50	Closed	PEREZ, Javier		
11 Feb 2023 05:27	Work Item Sign Off Reset	PEREZ, Javier		

Work Order 2023 00244			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
13 Feb 2023	12:39	Opened	FREEMAN, TIM			
13 Feb 2023	12:39	Discrepancy Added	FREEMAN, TIM		ETA squawk: ECU B Fail latched	
13 Feb 2023	14:50	Closed	ALkhraissi, Abdulrhman			

Work Order 2023 00253			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
16 Feb 2023 14:46	Opened	MEDINA, ROOSBER		
16 Feb 2023 14:46	Discrepancy Added	MEDINA, ROOSBER	ETA squawk: ECU failure	
17 Feb 2023 09:12	Parts Posted	PEREZ, Javier		
17 Feb 2023 11:14	Parts Posted	ALZUBAIDI, EYAD		
18 Feb 2023 05:32	Part Filled	ALZUBAIDI, EYAD	(4) LN9338-M8	
18 Feb 2023 05:33	Part Filled	ALZUBAIDI, EYAD	(1) MS9144-01_	
19 Feb 2023 15:57	Part Removed from Resource	ALENAZI, NAFEL	(1) P-853-16 serial # 20G677-K/G	
19 Feb 2023 15:57	Parts Posted	ALENAZI, NAFEL		
19 Feb 2023 15:57	Part Filled	ALENAZI, NAFEL	(1) P-853-16 serial # 18G1049-I/G	
19 Feb 2023 16:01	Work Item Sign Off Reset	PEREZ, Javier		
19 Feb 2023 16:15	Work Item Sign Off Reset	PEREZ, Javier		
20 Feb 2023 10:27	Part Installed on Resource	MEDINA, ROOSBER	(4) LN9338-M8	
20 Feb 2023 10:27	Part Installed on Resource	MEDINA, ROOSBER	(1) MS9144-01_	
20 Feb 2023 10:27	Part Installed on Resource	MEDINA, ROOSBER	(1) P-853-16 serial # 18G1049-I/G	
20 Feb 2023 10:27	Closed	MEDINA, ROOSBER		

Work Order 2023 00257			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
17 Feb 2023 15:01	Opened	PEREZ, Javier		
17 Feb 2023 15:01	Discrepancy Added	PEREZ, Javier	ENGINE TURBO IS LEAKING OIL	
18 Feb 2023 05:53	Parts Posted	CEPEDA, ALEJANDRO		
18 Feb 2023 09:08	Part Filled	ALENAZI, NAFEL	(1) E4A-00-410-BHY serial # XI5005137100012	
18 Feb 2023 09:08	Part Filled	ALENAZI, NAFEL	(2) DIN7603-12X16X2.0	
18 Feb 2023 09:08	Part Filled	ALENAZI, NAFEL	(2) DIN3771-46.2X3.55	
18 Feb 2023 09:08	Part Filled	ALENAZI, NAFEL	(1) E4A-05-000-104	
18 Feb 2023 09:08	Part Filled	ALENAZI, NAFEL	(1) 4002-N-3	
18 Feb 2023 09:09	Part Filled	ALENAZI, NAFEL	(4) 2142110	
18 Feb 2023 19:15	Parts Posted	CEPEDA, ALEJANDRO		
19 Feb 2023 08:18	Part Filled	ALENAZI, NAFEL	(12) CTB-4X11.8MM	
19 Feb 2023 15:42	Parts Posted	AL HAZMI, FAISAL		
19 Feb 2023 15:45	Part Filled	ALENAZI, NAFEL	(1) E4A-00-410-BHY serial # WJ5004456100071	
20 Feb 2023 09:20	Part Removed from Work Order	ALENAZI, NAFEL	(1) E4A-00-410-BHY serial # WJ5004456100071	
20 Feb 2023 09:20	Part Filled	ALENAZI, NAFEL	(1) E4A-00-410-000 serial # UJ5031027700071	
20 Feb 2023 10:36	Part Installed on Resource	MEDINA, ROOSBER	(2) DIN3771-46.2X3.55	
20 Feb 2023 10:36	Part Installed on Resource	MEDINA, ROOSBER	(1) E4A-05-000-104	
20 Feb 2023 10:36	Part Installed on Resource	MEDINA, ROOSBER	(1) 4002-N-3	
20 Feb 2023 10:36	Part Installed on Resource	MEDINA, ROOSBER	(4) 2142110	
20 Feb 2023 10:36	Part Installed on Resource	MEDINA, ROOSBER	(12) CTB-4X11.8MM	
20 Feb 2023 10:36	Part Installed on Resource	MEDINA, ROOSBER	(1) E4A-00-410-000 serial # UJ5031027700071	
20 Feb 2023 10:36	Part Installed on Resource	MEDINA, ROOSBER	(1) E4A-00-410-BHY serial # XI5005137100012	
20 Feb 2023 10:36	Part Installed on Resource	MEDINA, ROOSBER	(2) DIN7603-12X16X2.0	
20 Feb 2023 10:36	Closed	MEDINA, ROOSBER		

Work Order 2023 00263			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
20 Feb 2023	10:33	Opened	MEDINA, ROOSBER			
20 Feb 2023	10:33	Discrepancy Added	MEDINA, ROOSBER		DUE TO PROPELLER OVERSPEED GOVERNOR REPLACEMENT, MAINTENANCE FLIGHT TEST IS REQUIRED.	
21 Feb 2023	16:26	Closed	MEDINA, ROOSBER			

Work Order		2023 00270		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
24 Feb 2023	10:20	Opened		PEREZ, Javier			
24 Feb 2023	10:20	Discrepancy Added		PEREZ, Javier		Pilot Squawk: Chip found on lower portion of right wing during pre-flight check	
16 May 2023	14:02	Closed		ALkhraissi, Abdulrhman			

Work Order 2023 00310			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
01 Mar 2023 14:40	Opened	MEDINA, ROOSBER		
01 Mar 2023 14:40	Event Added	MEDINA, ROOSBER	MSB-E4-036/1 HIGH PRESSURE PUMP (HPP) INSPECTION AND REPLACEMENT	
25 Mar 2023 05:34	Parts Posted	MEDINA, ROOSBER		
13 Apr 2023 05:54	Part Filled	GADZAMA, SAMUEL	(1) E4A-30-200-000 serial # 12-01-09-03-00716	
13 Apr 2023 06:02	Part Removed from Work Order	GADZAMA, SAMUEL	(1) E4A-30-200-000 serial # 12-01-09-03-00716	
13 Apr 2023 06:04	Parts Posted	GADZAMA, SAMUEL		
13 Apr 2023 06:25	Part Removed from Resource	GADZAMA, SAMUEL	(1) E4A-30-000-000 serial # 20-03-04-02-00086	
13 Apr 2023 06:25	Parts Posted	GADZAMA, SAMUEL		
13 Apr 2023 06:26	Part Filled	GADZAMA, SAMUEL	(1) E4A-30-000-000 serial # 19-03-26-02-01686	
13 Apr 2023 07:03	Parts Posted	Al MOHAISEN, Muayed		
13 Apr 2023 08:49	Parts Posted	Ibrahim, ABDULLAH		
15 Apr 2023 09:27	Part Filled	ALENAZI, NAFEL	(2) DIN7603-12X16X2.0	
15 Apr 2023 09:28	Part Filled	ALENAZI, NAFEL	(2) DIN7603-A12X16-AL	
17 Apr 2023 12:00	Part Installed on Resource	MEDINA, ROOSBER	(2) DIN7603-12X16X2.0	
17 Apr 2023 12:00	Part Installed on Resource	MEDINA, ROOSBER	(2) DIN7603-A12X16-AL	
17 Apr 2023 12:00	Part Installed on Resource	MEDINA, ROOSBER	(1) E4A-30-000-000 serial # 19-03-26-02-01686	
17 Apr 2023 12:00	Closed	MEDINA, ROOSBER		

Work Order 2023 00329			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
04 Mar 2023 12:24	Opened	MEDINA, ROOSBER		
04 Mar 2023 12:24	Event Added	MEDINA, ROOSBER	MSB-E4-039 REV.3 OIL ANALYSIS AND PISTONS REPLACEMENT	
10 Mar 2023 09:39	Parts Posted	MILIBARI, SULTAN		
10 Mar 2023 09:45	Part Filled	ALZUBAIDI, EYAD	(1) PLT1MM76	
10 Mar 2023 13:52	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) PLT1MM76	
10 Mar 2023 13:52	Closed	ALkhraissi, Abdulrhman		

Work Order 2023 00394			Work Order Status: Closed		Resource: XF-35	
When	Action		Who	Details		
12 Mar 2023 08:53	Opened		MEDINA, ROOSBER	MSB 40NG-003 R15 SOFTWARE GARMIN G1000; APPROVED SOFTWARE SYS.		
12 Mar 2023 08:53	Event Added		MEDINA, ROOSBER			
03 Apr 2023 12:57	Closed		MEDINA, ROOSBER			

Work Order 2023 00412			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
15 Mar 2023	14:40	Opened	MEDINA, ROOSBER			
15 Mar 2023	14:40	Event Added	MEDINA, ROOSBER		MSB-E4-039 REV.3 OIL ANALYSIS AND PISTONS REPLACEMENT	
15 Mar 2023	14:56	Closed	ALkhraissi, Abdulrhman			

Work Order 2023 00464			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
25 Mar 2023	10:07	Opened	PEREZ, Javier			
25 Mar 2023	10:07	Event Added	PEREZ, Javier		MAGNETIC COMPASS	
17 May 2023	07:46	Closed	MEDINA, ROOSBER			

Work Order 2023 00477			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
30 Mar 2023 06:19	Opened	MEDINA, ROOSBER		
30 Mar 2023 06:19	Event Added	MEDINA, ROOSBER	FIRST AID KIT INSPECTION	
30 Mar 2023 06:34	Part Removed from Resource	ALZUBAIDI, EYAD	(1) TST-HC serial # HC-1876	
30 Mar 2023 06:34	Parts Posted	ALZUBAIDI, EYAD		
30 Mar 2023 06:42	Part Filled	ALZUBAIDI, EYAD	(1) TST-HC serial # X1871	
31 Mar 2023 06:11	Part Installed on Resource	MEDINA, ROOSBER	(1) TST-HC serial # X1871	
31 Mar 2023 06:11	Closed	MEDINA, ROOSBER		

Work Order 2023 00502			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
08 Apr 2023	05:27	Opened	MEDINA, ROOSBER			
08 Apr 2023	05:27	Discrepancy Added	MEDINA, ROOSBER		30 DAYS ENGINE RUN UP	
08 Apr 2023	12:57	Closed	PEREZ, Javier			
08 Apr 2023	13:00	Closed	MEDINA, ROOSBER			

Work Order 2023 00546			Work Order Status: Closed	Resource: XF-35
When	Action		Who	Details
17 Apr 2023 09:29	Opened		MEDINA, ROOSBER	
17 Apr 2023 09:29	Event Added		MEDINA, ROOSBER	900 HOUR TIME LIMITS UPDATE BY EASA AD 2019-0041
17 Apr 2023 09:29	Event Added		MEDINA, ROOSBER	FAA AD 2020-14-07 LIFE LIMITED TIMING CHAIN/INJECTORS
17 Apr 2023 09:29	Event Added		MEDINA, ROOSBER	MSB-E4-025/3 FUEL INJECTORS
17 Apr 2023 09:45	Closed		ALkhraissi, Abdulrhman	

Work Order 2023 00629			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
07 May 2023	04:27	Opened	PEREZ, Javier			
07 May 2023	04:27	Event Added	PEREZ, Javier		30 DAY ENGINE RUN	
07 May 2023	10:59	Closed	PEREZ, Javier			

Work Order 2023 00635			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
08 May 2023 04:27	Opened	PEREZ, Javier		
08 May 2023 04:27	Event Added	PEREZ, Javier	MAIN BATTERY CAPACITY TEST 12 MONTHS INTERVAL	
08 May 2023 04:28	Event Added	PEREZ, Javier	MAIN BATTERY CAP CHECK 1000 HOURS	
14 May 2023 09:50	Parts Posted	ALJEDAIE, YOUSEF		
14 May 2023 09:54	Part Filled	ALJEDAIE, YOUSEF	(1) RG24-15 serial # 40976346	
15 May 2023 08:21	Work Item Sign Off Reset	PEREZ, Javier		
15 May 2023 08:21	Work Item Sign Off Reset	PEREZ, Javier		
15 May 2023 08:26	Work Item Sign Off Reset	PEREZ, Javier		
15 May 2023 08:26	Work Item Sign Off Reset	PEREZ, Javier		
17 May 2023 07:31	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) RG24-15 serial # 40976346	
17 May 2023 07:31	Closed	ALkhraissi, Abdulrhman		

Work Order		2023 00653		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
09 May 2023	13:00	Opened		FREEMAN, TIM			
09 May 2023	13:00	Discrepancy Added		FREEMAN, TIM		VERIFY AND CONFIRM ACFT INSURANCE REMOVED FROM GRO TO FFR PER BUSINESS DEVELOPMENT DIRECTOR	
17 May 2023	12:30	Closed		MEDINA, ROOSBER			

Work Order		2023 00743		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
25 May 2023	06:18	Opened		MEDINA, ROOSBER			
25 May 2023	06:18	Discrepancy Added		MEDINA, ROOSBER		ETA squawk: ECU A fail	
25 May 2023	11:06	Closed		ALkhraissi, Abdulrhman			

Work Order 2023 00748			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
25 May 2023	06:56	Opened	MEDINA, ROOSBER			
25 May 2023	06:56	Event Added	MEDINA, ROOSBER		ACFT INSURANCE DUE	
25 May 2023	07:01	Closed	ALkhraissi, Abdulrhman			

Work Order		2023 00790		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
29 May 2023	11:41	Opened		FREEMAN, TIM			
29 May 2023	11:41	Discrepancy Added		FREEMAN, TIM		DEACTIVATE RACC SYSTEM FOR SAFETY	
29 May 2023	22:25	Closed		CEPEDA, ALEJANDRO			

Work Order 2023 00804			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
29 May 2023 13:00	Opened	FREEMAN, TIM		
29 May 2023 13:00	Discrepancy Added	FREEMAN, TIM	RACC INOP TILL FURTHER NOTICE. RESPONCE TO BURNT WIRES	
06 Jun 2023 20:36	Parts Posted	CEPEDA, ALEJANDRO		
06 Jun 2023 20:49	Part Filled	CEPEDA, ALEJANDRO	(1) DIN985-M5-A2	
06 Jun 2023 20:49	Part Filled	CEPEDA, ALEJANDRO	(1) MS21044N5	
07 Jun 2023 07:25	Part Removed from Work Order	ALENAZI, NAFEL	(1) DIN985-M5-A2	
07 Jun 2023 07:30	Parts Posted	MILIBARI, SULTAN		
07 Jun 2023 07:31	Part Filled	ALENAZI, NAFEL	(1) DIN985-M6-A2	
08 Jun 2023 06:38	Part Installed on Resource	GADZAMA, SAMUEL	(1) DIN985-M6-A2	
08 Jun 2023 06:38	Part Installed on Resource	GADZAMA, SAMUEL	(1) MS21044N5	
08 Jun 2023 06:38	Closed	GADZAMA, SAMUEL		

Work Order 2023 00839		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
31 May 2023 10:25	Opened	MILIBARI, SULTAN		
31 May 2023 10:25	Discrepancy Added	MILIBARI, SULTAN	PILOT REPORTED COMPASS OFF LIMITS.	
31 May 2023 14:17	Closed	ALkhraissi, Abdulrhman		

Work Order 2023 00890		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
10 Jun 2023 11:32	Opened	ALLWAIM, HASAN		
10 Jun 2023 11:32	Event Added	ALLWAIM, HASAN	300 HOUR ENGINE INSPECTION	
10 Jun 2023 11:33	Event Added	ALLWAIM, HASAN	ALTERNATOR/GENERATOR INSPECTION	
10 Jun 2023 11:33	Event Added	ALLWAIM, HASAN	100 HOUR AIRFRAME, PROPELLER AND ENGINE INSPECTION	
10 Jun 2023 11:33	Event Added	ALLWAIM, HASAN	AIRCRAFT LUBRICATION, 200 HRS EVERY 100 HRS	
10 Jun 2023 11:33	Event Added	ALLWAIM, HASAN	EASA AD 2016-0203 INSPECTION OF TURBO CHARGER V-BAND CLAMP	
10 Jun 2023 11:33	Event Added	ALLWAIM, HASAN	FAA AD 2016-23-03 INSPECTION OF TURBO CHARGER V-BAND CLAMP	
10 Jun 2023 11:34	Event Added	ALLWAIM, HASAN	MSB 40NG-046/2 INSPECTION OF TURBO CHARGER V-BAND CLAMP	
10 Jun 2023 11:42	Parts Posted	ALLWAIM, HASAN		
10 Jun 2023 13:14	Part Filled	ALENAZI, NAFEL	(7) 5W40 ENGINE OIL	
10 Jun 2023 13:14	Part Filled	ALENAZI, NAFEL	(2) SPIRAX-S6-GXME_20L	
10 Jun 2023 13:14	Part Filled	ALENAZI, NAFEL	(1) WK724_3	
10 Jun 2023 13:15	Part Filled	ALENAZI, NAFEL	(1) LN94-20020	
10 Jun 2023 13:15	Part Filled	ALENAZI, NAFEL	(5) PLT1MM30	
10 Jun 2023 13:15	Part Filled	ALENAZI, NAFEL	(5) PLT1MM76	
10 Jun 2023 13:15	Part Filled	ALENAZI, NAFEL	(1) E4A-00-301-KIT	
10 Jun 2023 13:34	Parts Posted	ALLWAIM, HASAN		
10 Jun 2023 13:45	Part Filled	ALENAZI, NAFEL	(1) DIN3771-26X2-FPM75	
10 Jun 2023 13:45	Part Filled	ALENAZI, NAFEL	(1) ORO375	
10 Jun 2023 13:45	Part Filled	ALENAZI, NAFEL	(1) E4A-70-000-806	
12 Jun 2023 05:18	Parts Posted	ALZUBAIDI, EYAD		
12 Jun 2023 05:31	Part Filled	MILIBARI, SULTAN	(1) E4A-41-100-801	
12 Jun 2023 05:51	Parts Posted	ALMUSAWI, ABDULLAH		
12 Jun 2023 05:54	Part Filled	MILIBARI, SULTAN	(1) LN94-20020	
12 Jun 2023 11:09	Part Removed from Work Order	ALENAZI, NAFEL	(1) LN94-20020	
19 Jun 2023 08:32	Work Item Sign Off Reset	ALZUBAIDI, EYAD		
19 Jun 2023 08:34	Work Item Sign Off Reset	ALZUBAIDI, EYAD		
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(1) DIN3771-26X2-FPM75	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(1) E4A-41-100-801	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(1) E4A-70-000-806	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(1) ORO375	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(1) WK724_3	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(2) SPIRAX-S6-GXME_20L	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(5) PLT1MM76	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(5) PLT1MM30	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(1) LN94-20020	

Work Order		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(1) E4A-00-301-KIT	
23 Jun 2023 10:01	Part Installed on Resource	MEDINA, ROOSBER	(7) 5W40 ENGINE OIL	
23 Jun 2023 10:01	Closed	MEDINA, ROOSBER		

Work Order 2023 00898			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
12 Jun 2023 06:10	Opened	MILIBARI, SULTAN		
12 Jun 2023 06:10	Discrepancy Added	MILIBARI, SULTAN	300 HOUR INSPECTION FINDING	
12 Jun 2023 06:10	Parts Posted	MILIBARI, SULTAN		
12 Jun 2023 06:11	Part Filled	MILIBARI, SULTAN	(1) DA4-1127-10-040	
12 Jun 2023 11:57	Discrepancy Added	GADZAMA, SAMUEL	LH AND RH OVERWING SEAL DISBONED AT THE INNER FLAP TRAILING EDGE.	
12 Jun 2023 11:58	Discrepancy Added	GADZAMA, SAMUEL	FADED STALL WARNING DECAL.	
20 Jun 2023 07:23	Work Item Sign Off Reset	ALZUBAIDI, EYAD		
23 Jun 2023 10:32	Part Installed on Resource	MEDINA, ROOSBER	(1) DA4-1127-10-040	
23 Jun 2023 10:32	Closed	MEDINA, ROOSBER		

Work Order 2023 00923			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
15 Jun 2023	21:32	Opened	CEPEDA, ALEJANDRO			
15 Jun 2023	21:32	Discrepancy Added	CEPEDA, ALEJANDRO		MAGNETIC COMPASS CHECK REQUIRED	
19 Jun 2023	14:38	Work Item Sign Off Reset	CEPEDA, ALEJANDRO			
19 Jun 2023	14:40	Closed	CEPEDA, ALEJANDRO			
20 Jun 2023	12:40	Work Item Sign Off Reset	ALkhraissi, Abdulrhman			
20 Jun 2023	12:43	Closed	CEPEDA, ALEJANDRO			

Work Order 2023 00935			Work Order Status: Closed		Resource: XF-35	
When		Action	Who	Details		
19 Jun 2023 08:37	Opened		GADZAMA, SAMUEL			
19 Jun 2023 08:37	Discrepancy Added		GADZAMA, SAMUEL	AIR FILTER REPLACEMENT AFTER 100 HOURS INSPECTION		
23 Jun 2023 09:49	Discrepancy Added		MEDINA, ROOSBER	ENGINE GROUND CHECK REQUIRED		
06 Jul 2023 10:20	Parts Posted		FREEMAN, TIM			
06 Jul 2023 10:25	Part Filled		MILIBARI, SULTAN	(1) RU-1620		
06 Jul 2023 21:07	Part Installed on Resource		CEPEDA, ALEJANDRO	(1) RU-1620		
06 Jul 2023 21:07	Closed		CEPEDA, ALEJANDRO			

Work Order		2023 00940		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
20 Jun 2023	06:02	Opened		GADZAMA, SAMUEL			
20 Jun 2023	06:02	Discrepancy Added		GADZAMA, SAMUEL		UPPER COWLING MISSING 1 EACH CAMLOCK.	
06 Jul 2023	03:59	Closed		GADZAMA, SAMUEL			

Work Order 2023 01041		Work Order Status: Closed		Resource: XF-35	
When Action		Who		Details	
06 Jul 2023	15:44	Opened	FREEMAN, TIM		
06 Jul 2023	15:44	Discrepancy Added	FREEMAN, TIM		CALIBRATE COMPASS WITH RACC OFF, COPY HEADING REQUIRED WITH RACC ON AS REFERENCE ONLY TO CREW.
06 Jul 2023	16:02	Closed	CEPEDA, ALEJANDRO		

Work Order 2023 01054			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
10 Jul 2023	06:03	Opened	FREEMAN, TIM			
10 Jul 2023	06:03	Discrepancy Added	FREEMAN, TIM		CHIP ON PROP #2 TRAILING EDGE	
10 Jul 2023	23:22	Closed	CEPEDA, ALEJANDRO			

Work Order 2023 01115			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
23 Jul 2023 15:22	Opened	FREEMAN, TIM		
23 Jul 2023 15:22	Event Added	FREEMAN, TIM	MSB-E4-039 REV.3 OIL ANALYSIS AND PISTONS REPLACEMENT	
24 Jul 2023 04:56	Parts Posted	ALZUBAIDI, EYAD		
24 Jul 2023 05:50	Part Filled	MILIBARI, SULTAN	(1) PLT4SM30	
24 Jul 2023 05:51	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) PLT4SM30	
24 Jul 2023 05:51	Closed	ALkhraissi, Abdulrhman		

Work Order 2023 01147			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
27 Jul 2023 16:25	Opened	CEPEDA, ALEJANDRO		
27 Jul 2023 16:25	Event Added	CEPEDA, ALEJANDRO	ELT BATTERY REPLACEMENT	
27 Jul 2023 16:27	Parts Posted	CEPEDA, ALEJANDRO		
27 Jul 2023 16:39	Part Filled	MILIBARI, SULTAN	(1) DIN985-M6-A2	
27 Jul 2023 16:40	Part Filled	MILIBARI, SULTAN	(1) MS21044N5	
27 Jul 2023 22:39	Work Item Sign Off Reset	CEPEDA, ALEJANDRO		
28 Jul 2023 06:31	Part Installed on Resource	MEDINA, ROOSBER	(1) MS21044N5	
28 Jul 2023 06:31	Part Installed on Resource	MEDINA, ROOSBER	(1) DIN985-M6-A2	
28 Jul 2023 06:31	Closed	MEDINA, ROOSBER		

Work Order 2023 01149			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
27 Jul 2023	22:16	Opened	CEPEDA, ALEJANDRO			
27 Jul 2023	22:16	Discrepancy Added	CEPEDA, ALEJANDRO		RACC INSPECTION	
27 Jul 2023	22:37	Closed	CEPEDA, ALEJANDRO			

Work Order 2023 01165			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
30 Jul 2023	13:14	Opened	MEDINA, ROOSBER			
30 Jul 2023	13:14	Event Added	MEDINA, ROOSBER		100 HOUR RACC INSPECTION	
30 Jul 2023	13:23	Closed	MEDINA, ROOSBER			

Work Order 2023 01259			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
01 Sep 2023 05:33	Opened	ALLWAIM, HASAN		
01 Sep 2023 05:33	Event Added	ALLWAIM, HASAN	ANNUAL INSPECTION	
01 Sep 2023 05:33	Event Added	ALLWAIM, HASAN	200 HOUR FDR INSPECTION	
01 Sep 2023 05:33	Event Added	ALLWAIM, HASAN	RACC SYSTEM	
01 Sep 2023 05:33	Event Added	ALLWAIM, HASAN	ECU BATTERY REPLACEMENT	
01 Sep 2023 05:34	Event Added	ALLWAIM, HASAN	ELT FUNCTION TEST	
01 Sep 2023 05:34	Event Added	ALLWAIM, HASAN	200 HOUR INSPECTION AIRFRAME, PROPELLER AND ENGINE INSPECTION	
01 Sep 2023 05:34	Event Added	ALLWAIM, HASAN	FIRE EXTINGUISHER ANNUAL INSPECTION AMEREX	
01 Sep 2023 05:34	Event Added	ALLWAIM, HASAN	AUTOPILOT GFC700 MECHANICAL CHECK	
01 Sep 2023 09:53	Part Removed from Resource	ALZUBAIDI, EYAD	(1) E4A-52-000-KIT	
01 Sep 2023 09:53	Parts Posted	ALZUBAIDI, EYAD		
01 Sep 2023 11:04	Part Filled	ALLWAIM, HASAN	(7) 5W40 ENGINE OIL	
01 Sep 2023 11:04	Part Filled	ALLWAIM, HASAN	(1) E4A-52-000-KIT	
01 Sep 2023 11:04	Part Filled	ALLWAIM, HASAN	(1) E4A-70-000-806	
01 Sep 2023 11:04	Part Filled	ALLWAIM, HASAN	(1) RU-1620	
01 Sep 2023 11:05	Part Filled	ALLWAIM, HASAN	(1) ORO375	
01 Sep 2023 11:05	Part Filled	ALLWAIM, HASAN	(1) DIN3771-26X2-FPM75	
01 Sep 2023 11:05	Part Filled	ALLWAIM, HASAN	(1) WK724_3	
01 Sep 2023 11:05	Part Filled	ALLWAIM, HASAN	(1) LN94-20020	
01 Sep 2023 11:05	Part Filled	ALLWAIM, HASAN	(2) SPIRAX-S6-GXME_20L	
02 Sep 2023 05:42	Event Added	ALLWAIM, HASAN	100 HOUR AIRFRAME, PROPELLER AND ENGINE INSPECTION	
02 Sep 2023 05:43	Event Added	ALLWAIM, HASAN	AIRCRAFT LUBRICATION, 200 HRS EVERY 100 HRS	
02 Sep 2023 05:43	Event Added	ALLWAIM, HASAN	BRAKE FLUID FLUSH	
02 Sep 2023 05:43	Event Added	ALLWAIM, HASAN	FAA AD 2016-23-03 INSPECTION OF TURBO CHARGER V-BAND CLAMP	
02 Sep 2023 05:43	Event Added	ALLWAIM, HASAN	EASA AD 2016-0203 INSPECTION OF TURBO CHARGER V-BAND CLAMP	
02 Sep 2023 05:44	Event Added	ALLWAIM, HASAN	MSB 40NG-046/2 INSPECTION OF TURBO CHARGER V-BAND CLAMP	
02 Sep 2023 06:15	Event Added	ALLWAIM, HASAN	MSB-E4-039 REV.3 OIL ANALYSIS AND PISTONS REPLACEMENT	
04 Sep 2023 05:05	Parts Posted	ALLWAIM, HASAN		
04 Sep 2023 05:55	Part Filled	ALLWAIM, HASAN	(2) LC-R127R2PG	
09 Sep 2023 13:34	Remove Event	PEREZ, Javier	NEED CORRECTION	
11 Sep 2023 08:50	Remove Event	ALLWAIM, HASAN	NOT APPLICABLE	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(1) ORO375	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(1) RU-1620	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(1) E4A-70-000-806	

Work Order			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(1) E4A-52-000-KIT	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(1) WK724_3	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(1) DIN3771-26X2-FPM75	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(7) 5W40 ENGINE OIL	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(2) SPIRAX-S6-GXME_20L	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(1) LN94-20020	
11 Sep 2023 14:16	Part Installed on Resource	PEREZ, Javier	(2) LC-R127R2PG	
11 Sep 2023 14:16	Closed	PEREZ, Javier		

Work Order 2023 01264			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
01 Sep 2023 11:55	Opened	PEREZ, Javier		
01 Sep 2023 11:55	Discrepancy Added	PEREZ, Javier	ANNUAL INSPECTION FINDINGS	
01 Sep 2023 11:57	Discrepancy Added	PEREZ, Javier	DURING PRE INSPECTION ENGINE RUN, COOLANT TEMPERATURE REACHED RED RANGE AND ENG TEMP MESSAGE WAS DISPLAYED	
10 Sep 2023 11:15	Discrepancy Added	PEREZ, Javier	FDR SYSTEM GPS INFORMATION IS NOT DISPLAYED IN IAERO SOFTWARE	
10 Sep 2023 11:16	Discrepancy Added	PEREZ, Javier	BRAKE FLUID IS LEAKING AT COPILOT SIDE FLOOR	
10 Sep 2023 11:17	Discrepancy Added	PEREZ, Javier	TURBOCHARGER INTAKE DUCT PROTECTION IS TURNED	
10 Sep 2023 11:18	Discrepancy Added	PEREZ, Javier	SIGN OF OIL LEAK ON ENG CASE AT TURBO CHARGER AREA	
10 Sep 2023 11:19	Discrepancy Added	PEREZ, Javier	VENT HOSE IS TURNED FWD OF INSTRUMENT GRARESHIELD	
10 Sep 2023 11:20	Discrepancy Added	PEREZ, Javier	T/E FLAP SUPORT RUBBER BOOT DETACHED ON BOTHSIDE BELOW PAX SEAT	
10 Sep 2023 11:21	Discrepancy Added	PEREZ, Javier	LH AND RH MLG TIRES WORN	
10 Sep 2023 13:37	Discrepancy Added	PEREZ, Javier	SERVICE AND INSTALL RACC	
11 Sep 2023 05:17	Parts Posted	FREEMAN, TIM		
11 Sep 2023 09:06	Parts Posted	ALZUBAIDI, EYAD		
11 Sep 2023 09:08	Part Filled	MILIBARI, SULTAN	(1) 079-00300	
11 Sep 2023 11:13	Discrepancy Added	ALZUBAIDI, EYAD	DRAIN SCREW ON R/H BRAKE CALIPER BROKEN	
12 Sep 2023 10:41	Parts Posted	ALHAWAS, BADER		
12 Sep 2023 10:42	Part Filled	MILIBARI, SULTAN	(1) DIN125-A4.3-A2	
12 Sep 2023 11:25	Part Removed from Work Order	MILIBARI, SULTAN	(1) DIN125-A4.3-A2	
12 Sep 2023 11:30	Parts Posted	MILIBARI, SULTAN		
12 Sep 2023 11:30	Part Filled	MILIBARI, SULTAN	(1) DIN125-A5.3-A2	
12 Sep 2023 12:23	Discrepancy Added	ALLWAIM, HASAN	LH STEP PLACARD MISING	
12 Sep 2023 13:14	Discrepancy Added	ALLWAIM, HASAN	FINISH MAIN BATTERY INSTALLATION 1 CLAMP NUT MISING	
14 Sep 2023 06:46	Parts Posted	Ibrahim, ABDULLAH		
14 Sep 2023 06:46	Part Filled	MILIBARI, SULTAN	(1) CAT6	
14 Sep 2023 06:47	Part Filled	MILIBARI, SULTAN	(1) DIN985-M6-A2	
14 Sep 2023 06:47	Part Filled	MILIBARI, SULTAN	(1) MS21044N5	
14 Sep 2023 08:35	Work Item Sign Off Reset	Ibrahim, ABDULLAH		
14 Sep 2023 09:16	Parts Posted	MILIBARI, SULTAN		
14 Sep 2023 09:16	Part Filled	MILIBARI, SULTAN	(1) DA4-5300-61-04_2	
14 Sep 2023 12:30	Parts Posted	MILIBARI, SULTAN		
14 Sep 2023 12:30	Part Filled	MILIBARI, SULTAN	(2) DIN7603-14X18X2.0	

Work Order		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
14 Sep 2023 13:02	Part Removed from Work Order	MILIBARI, SULTAN	(2) DIN7603-14X18X2.0	
14 Sep 2023 13:02	Parts Posted	MILIBARI, SULTAN		
14 Sep 2023 13:03	Part Filled	MILIBARI, SULTAN	(2) DIN7603-12X16X2.0	
18 Sep 2023 08:20	Parts Posted	MILIBARI, SULTAN		
18 Sep 2023 08:20	Part Filled	MILIBARI, SULTAN	(1) E4A-40-100-000	
19 Sep 2023 12:46	Part Installed on Resource	PEREZ, Javier	(1) DIN125-A5.3-A2	
19 Sep 2023 12:46	Part Installed on Resource	PEREZ, Javier	(1) MS21044N5	
19 Sep 2023 12:46	Part Installed on Resource	PEREZ, Javier	(1) DIN985-M6-A2	
19 Sep 2023 12:46	Part Installed on Resource	PEREZ, Javier	(2) DIN7603-12X16X2.0	
19 Sep 2023 12:46	Part Installed on Resource	PEREZ, Javier	(1) CAT6	
19 Sep 2023 12:46	Part Installed on Resource	PEREZ, Javier	(1) 079-00300	
19 Sep 2023 12:46	Part Installed on Resource	PEREZ, Javier	(1) DA4-5300-61-04_2	
19 Sep 2023 12:46	Part Installed on Resource	PEREZ, Javier	(1) E4A-40-100-000	
19 Sep 2023 12:46	Closed	PEREZ, Javier		

Work Order		2023 01265		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
01 Sep 2023	12:48	Opened		PEREZ, Javier			
01 Sep 2023	12:48	Event Added		PEREZ, Javier		MAIN BATTERY CAPACITY TEST 12 MONTHS INTERVAL	
01 Sep 2023	12:49	Event Added		PEREZ, Javier		MAIN BATTERY CAP CHECK 1000 HOURS	
12 Sep 2023	04:38	Work Item Sign Off Reset		PEREZ, Javier			
12 Sep 2023	04:50	Work Item Sign Off Reset		PEREZ, Javier			
12 Sep 2023	08:30	Closed		PEREZ, Javier			

Work Order 2023 01267			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
02 Sep 2023	05:43	Opened	ALLWAIM, HASAN			
02 Sep 2023	05:43	Event Added	ALLWAIM, HASAN		MAINTENACE TEST FLIGHT AFTER 200 HOUR INSPECTION	
03 Oct 2023	13:10	Closed	PEREZ, Javier			

Work Order 2023 01301			Work Order Status: Closed		Resource: XF-35	
When		Action	Who		Details	
09 Sep 2023	13:34	Opened	PEREZ, Javier		BRAKE FLUID FLUSH	
09 Sep 2023	13:34	Event Added	PEREZ, Javier			
11 Sep 2023	07:30	Closed	PEREZ, Javier			

Work Order	2023 01312	Work Order Status: Closed		Resource: XF-35	
When		Action	Who	Details	
12 Sep 2023 07:14		Opened	PEREZ, Javier		
12 Sep 2023 07:14		Event Added	PEREZ, Javier	WEIGHT AND BALANCE 36 MOTHS / GACA 91.11	
12 Sep 2023 07:14		Discrepancy Added	PEREZ, Javier	DEFUEL DE AICRAFT FOR W/B	
12 Sep 2023 07:14		Discrepancy Added	PEREZ, Javier	INSTALL LH AND RH FUEL DRAIN VALVES	
12 Sep 2023 13:05		Work Item Sign Off Reset	PEREZ, Javier		
15 Sep 2023 05:26		Parts Posted	ALTHEYAB, SALEH		
15 Sep 2023 05:28		Part Filled	ALTHEYAB, SALEH	(2) DA4-9028-17-02	
15 Sep 2023 12:27		Part Installed on Resource	FREEMAN, TIM	(2) DA4-9028-17-02	
15 Sep 2023 12:27		Closed	FREEMAN, TIM		

Work Order 2023 01428		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
23 Oct 2023 12:52	Opened	ALTHEYAB, SALEH		
23 Oct 2023 12:52	Event Added	ALTHEYAB, SALEH	MSB-E4-039 REV.3 OIL ANALYSIS AND PISTONS REPLACEMENT	
23 Oct 2023 13:24	Discrepancy Added	ALkhraissi, Abdulrhman	ETA squawk: msb-39	
23 Oct 2023 13:55	Work Item Sign Off Reset	Al MOHAISEN, Muayed		
23 Oct 2023 14:01	Closed	ALkhraissi, Abdulrhman		

Work Order		2023 01429		Work Order Status: Closed		Resource: XF-35	
When		Action		Who		Details	
23 Oct 2023	12:56	Opened		ALTHEYAB, SALEH			
23 Oct 2023	12:56	Discrepancy Added		ALTHEYAB, SALEH		DISCONNECT ELT BATT FOR EXPIRY DATE VERIFICATION, PERFORM ELT TEST AT INSTALATION.	
23 Oct 2023	14:02	Closed		ALkhraissi, Abdulrhman			

Work Order 2023 01457			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
29 Oct 2023 13:56	Opened	FREEMAN, TIM		
29 Oct 2023 13:56	Discrepancy Added	FREEMAN, TIM	ETA squawk: Tire has flat spot.	
29 Oct 2023 13:57	Parts Posted	FREEMAN, TIM		
28 Nov 2023 05:51	Discrepancy Added	ALkhraissi, Abdulrhman	100H INSP FINDINGS	
28 Nov 2023 05:51	Discrepancy Added	ALkhraissi, Abdulrhman	NOSE WHEEL TIRE WEATHER ATTACKED	
28 Nov 2023 05:51	Discrepancy Added	ALkhraissi, Abdulrhman	RH MAIN WHEEL WORN	
28 Nov 2023 06:57	Parts Posted	ALkhraissi, Abdulrhman		
28 Nov 2023 07:05	Parts Posted	ALkhraissi, Abdulrhman		
28 Nov 2023 07:28	Part Filled	MILIBARI, SULTAN	(1) 40-77ASSY serial # S681/S708	
28 Nov 2023 07:29	Part Filled	MILIBARI, SULTAN	(1) 40-414ASSY serial # S901/S592	
28 Nov 2023 07:29	Part Filled	MILIBARI, SULTAN	(1) LN94-20020	
28 Nov 2023 07:30	Part Filled	MILIBARI, SULTAN	(2) 066-14100	
28 Nov 2023 07:30	Part Filled	MILIBARI, SULTAN	(2) 066-14100	
28 Nov 2023 07:30	Part Filled	MILIBARI, SULTAN	(12) 105-00200	
28 Nov 2023 07:37	Parts Posted	MILIBARI, SULTAN		
28 Nov 2023 07:44	Part Filled	MILIBARI, SULTAN	(1) 40-414ASSY serial # T569/T581	
29 Nov 2023 08:34	Part Installed on Resource	ALkhraissi, Abdulrhman	(2) 066-14100	
29 Nov 2023 08:34	Part Installed on Resource	ALkhraissi, Abdulrhman	(2) 066-14100	
29 Nov 2023 08:34	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) 40-414ASSY serial # T569/T581	
29 Nov 2023 08:34	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) 40-414ASSY serial # S901/S592	
29 Nov 2023 08:34	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) 40-77ASSY serial # S681/S708	
29 Nov 2023 08:34	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) LN94-20020	
29 Nov 2023 08:34	Part Installed on Resource	ALkhraissi, Abdulrhman	(12) 105-00200	
29 Nov 2023 08:34	Closed	ALkhraissi, Abdulrhman		

Work Order 2023 01481		Work Order Status: Closed		Resource: XF-35
When	Action	Who	Details	
01 Nov 2023 06:24	Opened	ALLWAIM, HASAN		
01 Nov 2023 06:24	Event Added	ALLWAIM, HASAN	FIRST AID KIT INSPECTION	
01 Nov 2023 06:25	Part Removed from Resource	ALLWAIM, HASAN	(1) TST-HC serial # X1871	
01 Nov 2023 06:25	Parts Posted	ALLWAIM, HASAN		
01 Nov 2023 06:29	Part Filled	PEREZ, Javier	(1) DETTOL-W1402	
01 Nov 2023 06:29	Part Filled	PEREZ, Javier	(1) TST-HC serial # E156806	
01 Nov 2023 10:58	Part Installed on Resource	PEREZ, Javier	(1) TST-HC serial # E156806	
01 Nov 2023 10:58	Part Installed on Resource	PEREZ, Javier	(1) DETTOL-W1402	
01 Nov 2023 10:58	Closed	PEREZ, Javier		

Work Order 2023 01561			Work Order Status: Closed	Resource: XF-35
When	Action	Who	Details	
26 Nov 2023 07:59	Opened	ALkhraissi, Abdulrhman		
26 Nov 2023 07:59	Event Added	ALkhraissi, Abdulrhman	MSB 40NG-080 Inspection of starter wiring	
26 Nov 2023 08:02	Event Added	ALkhraissi, Abdulrhman	MSB-E4-003/30 SOFTWARE AND HARDWARE VERSIONS OF THE E4 ENGINE S	
26 Nov 2023 08:02	Event Added	ALkhraissi, Abdulrhman	FAA AD 2016-23-03 INSPECTION OF TURBO CHARGER V-BAND CLAMP	
26 Nov 2023 08:02	Event Added	ALkhraissi, Abdulrhman	EASA AD 2016-0203 INSPECTION OF TURBO CHARGER V-BAND CLAMP	
26 Nov 2023 08:02	Event Added	ALkhraissi, Abdulrhman	100 HOUR AIRFRAME, PROPELLER AND ENGINE INSPECTION	
26 Nov 2023 08:03	Event Added	ALkhraissi, Abdulrhman	100 HOUR RACC INSPECTION	
26 Nov 2023 08:03	Event Added	ALkhraissi, Abdulrhman	MSB-E4-039 REV.3 OIL ANALYSIS AND PISTONS REPLACEMENT	
26 Nov 2023 08:46	Parts Posted	ALkhraissi, Abdulrhman		
26 Nov 2023 08:58	Part Filled	MILIBARI, SULTAN	(1) ORO375	
26 Nov 2023 08:58	Part Filled	MILIBARI, SULTAN	(2) SPIRAX-S6-GXME_20L	
26 Nov 2023 08:59	Part Filled	MILIBARI, SULTAN	(1) DIN3771-26X2-FPM75	
26 Nov 2023 08:59	Part Filled	MILIBARI, SULTAN	(7) 5W40 ENGINE OIL	
26 Nov 2023 08:59	Part Filled	MILIBARI, SULTAN	(1) RU-1620	
26 Nov 2023 08:59	Part Filled	MILIBARI, SULTAN	(1) E4A-52-000-KIT	
26 Nov 2023 09:15	Parts Posted	ALkhraissi, Abdulrhman		
26 Nov 2023 09:15	Part Filled	MILIBARI, SULTAN	(1) WK724_3	
29 Nov 2023 07:32	Event Added	ALkhraissi, Abdulrhman	AIRCRAFT LUBRICATION, 200 HRS EVERY 100 HRS	
29 Nov 2023 07:35	Event Added	ALkhraissi, Abdulrhman	MSB 40NG-046/2 INSPECTION OF TURBO CHARGER V-BAND CLAMP	
29 Nov 2023 08:36	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) E4A-52-000-KIT	
29 Nov 2023 08:36	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) RU-1620	
29 Nov 2023 08:36	Part Installed on Resource	ALkhraissi, Abdulrhman	(7) 5W40 ENGINE OIL	
29 Nov 2023 08:36	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) DIN3771-26X2-FPM75	
29 Nov 2023 08:36	Part Installed on Resource	ALkhraissi, Abdulrhman	(2) SPIRAX-S6-GXME_20L	
29 Nov 2023 08:36	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) ORO375	
29 Nov 2023 08:36	Part Installed on Resource	ALkhraissi, Abdulrhman	(1) WK724_3	
29 Nov 2023 08:36	Closed	ALkhraissi, Abdulrhman		